



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg
(199806235M)

Vehicle No. **GBE2995R NISSAN NV200 1.5**

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR'S ADJUSTMENT	
	<u>PARTS (LIST ITEMS)</u>					
1	Rear door LH			1180.00		
1	Rear door weatherstrip LH			85.00		
1	Rear door LH emblem "NV 200"			75.00		
1	Rear door LH logo badge			60.00		
1	Rear door RH			950.00		
1	Rear door weatherstrip RH			85.00		
1	Rear door RH emblem "dCi"			85.00		
2	Rear door LH hinge upper and lower @2*\$105			210.00		
2	Rear door RH hinge upper and lower @2*\$105			210.00		
1	Rear door LH center garnish			210.00		
1	Rear bumper			490.00		
1	Rear bumper side retainer LH/RH @2*\$30			60.00		
1	Tail lamp RH/LH @2*140			280.00		
1	Rear door LH top brake lamp			180.00		
1	Rear door LH lock			105.00		
1	End panel top garnish			75.00		
		Part Items Total:		4340.00		
			15%	651.00		
				4991.00		
	<u>SPECIAL NETT ITEMS</u>					
1	Rear bumper clips			35.00		
1	70km/h decal sticker			15.00		
1	6 pax decal sticker			15.00		
1	Car plate with holder			35.00		
1	Rear reverse sensor			200.00		
1	Rear windscreen solar film LH/RH			300.00		
		SN Items Total:		600.00		
		Total Parts		5591.00		



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. GBE2995R NISSAN NV200 1.5

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	600.00	
3	To perform anti-rust treatment on affected areas	40.00	
4	To remove and refix/replace wiring system, reverse sensor at accident damaged area and check for all electrical proper function	100.00	
5	To carried out remove and refix rear windscreen RH	100.00	
6	To carried out remove and refix rear windscreen LH	100.00	
	Labour Total :	1740.00	
	TOTAL (PARTS & LABOUR):	7331.00	