

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/III/AMK

Claim Type: Third Party

Accident Date: 24/01/2021

TP Veh Reg No: SML5598S

Estimate No: ES2190352/AMK

Date: 13 Apr 2021

Policy No: 5113701522-01

Veh Reg No: SMR7378R

Make/Model: TOYOTA VIOS 1.5E A

Chassis No: MR2B23F3601190038

Engine No: 2NR5395377

Reg. Date: 31/10/2019

Estimate Repair Cost to Vehicle No :SMR7378R

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER	452.00	1 PC	452.00	X
2 REAR BUMPER RH SIDE RETAINER	122.90	1 PC	122.90	X
3 REAR BUMPER CLIP	3.50	5 PC	17.50	X
			592.40	
		Less 25%	148.10	444.30
Labour				
4 REMOVE & REFIX REAR BUMPER & ATTACHMENTS,PARKING SENSORS,TAILLAMP & REALIGN THE SAME	300	1 LA	300.00	180
5 PUTTY & RESPRAY REAR BUMPER & PARKING SENSORS,REAR RH FENDER & ALL AFFECTED AREAS	400	1 LA	400.00	360
			700.00	700.00
			Total	S\$ 1,144.30
			Add GST @ 7%	80.10
			Total Amount Payable	S\$ 1,224.40

P/P = \$540.00

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

NOT Attached
Resurvey After Paint
2 days

For Cheng Hoe Motor Pte Ltd

Dorlyn

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: