



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0090/2021/CCS
DATE : 27-Jan-21
WIP : 13224

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR VENU MOTURU
ADDRESS : BLK 633 JURONG WEST ST 65
#14-306
SINGAPORE 640633
TELEPHONE : HP +65 98802621
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800142088-01
VEHICLE NO : **SMF 8938 G**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 28/11/2018
ENGINE NO : CZE 846224
CHASSIS NO : WAUZZZ8V6K1004520
MILEAGE :
DATE IN : 27-Jan-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Jan-21
PLACE OF ACCIDENT : NEAR AYE, TUAS ROAD UNDERPASS EXIT 41

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 8938 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	✓
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	✓
3	TO REMOVE AND TRANSFER BOTH HEADLIGHTS'S CONTROL UNI AND POWER MODULE.	S/N \$ 700.00	300
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	2750.
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND BOTH FRONT FENDERS.	\$ 4,000.00	2300 4 x 550 = 2200 Hinged = 100 2300
6	TO RECOVER AND TOW BACK VEHICLE FROM SCENE OF ACCIDENT	S/N \$ 280.00	X.
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192.
TOTAL LABOUR CHARGES		: \$ 12,444.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 8938 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Disloded</i>	1	\$ 1,987.00	✓
2 FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 187.00	+
3 FRONT BUMPER GUIDE - LH/RH <i>new</i>	2	\$ 78.00	+
4 FRONT BUMPER GRILLE - LOWER <i>ambd</i>	1	\$ 160.00	✓
5 FRONT BUMPER CLOSING ELEMENT - LOWER <i>new</i>	1	\$ 536.00	+
6 FRONT BUMPER CLOSING ELEMENT - LH/RH <i>?</i>	2	\$ 594.00	?
7 FRONT BUMPER COVER TRIM - LH/RH <i>new</i>	2	\$ 326.00	+
8 FRONT BUMPER ADAPTER - LH/RH <i>new</i>	2	\$ 76.00	+
9 RADIATOR GRILLE <i>ambd</i>	1	\$ 1,406.00	✓
10 RADIATOR GRILLE CLOSING ELEMENT <i>?</i>	1	\$ 191.00	?
11 FRONT BUMPER AIR GRILLE - LH/RH <i>new LH ambd</i>	2	\$ 376.00 188.	
12 FRONT REINFORCEMENT BEAM <i>?</i>	1	\$ 795.00	?
13 FRONT BUMPER FOAM FILLER <i>?</i>	1	\$ 189.00	?
14 FRONT BUMPER FOAM COVER <i>?</i>	1	\$ 122.00	?
15 STICKER FOR AIR CONDITIONER <i>2 sides</i>	1	\$ 8.00	✓
16 SIGN 'CAUTION' STICKER	1	\$ 14.00	✓
17 SIGNAL HORN - LH/RH <i>?</i>	2	\$ 400.00	?
18 FRONT FENDER - LH/RH <i>RH Rys, LH Rys</i>	2	\$ 1,702.00	+
19 FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 72.00	+
20 FRONT FENDER BRACKET - RH FRT <i>new</i>	1	\$ 39.00	+
SUB TOTAL SPARE PARTS	:	\$ 9,258.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 8938 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 FRONT FENDER BRACKET - RH REAR	1	\$	28.00	✓
22 FRONT FENDER BRACE - RH	1	\$	96.00	+
23 FRONT FENDER POP RIVET	10	\$	33.00	✓
24 FRONT WHEEL HOUSING LINER - LH/RH	2	\$	338.00	+
25 WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$	89.00	+
26 BONNET <i>Dented</i>	1	\$	3,134.00	✓
27 BONNET ATTACHMENT PARTS <i>Ne m</i>	1	\$	165.00	+
28 BONNET HINGE - LH/RH <i>Bent</i>	2	\$	124.00	✓
29 BONNET CATCH HOOK <i>Ne m ?</i>	1	\$	90.00	✓
30 BONNET LOCK STRIKER - LH/RH <i>Bent</i>	2	\$	220.00	✓
31 BONNET EDGE PROTECTION <i>Ne m</i>	1	\$	28.00	✓
32 BONNET LOCK - LH/RH <i>Damaged</i>	2	\$	427.00	✓
33 BONNET HINGE COVER - LH/RH <i>Ne m</i>	2	\$	8.00	+
34 BONNET BOWDEN CABLE <i>Tanned</i>	1	\$	58.00	✓
35 BONNET LOCK CABLE <i>Ne ?</i>	1	\$	74.00	?
36 BONNET BOWDEN CABLE COVER <i>?</i>	1	\$	10.00	?
37 BONNET SOUND ABSORBER <i>Ne m</i>	1	\$	219.00	+
38 PLENUM CHAMBER COVER <i>Ne m</i>	1	\$	179.00	+
39 LED HEADLIGHT - LH/RH <i>LH cracked, RH bent</i>	2	\$	10,910.00	✓
40 MAIN LIGHT POWER MODULE <i>Ne m</i>	1	\$	758.00	+
SUB TOTAL SPARE PARTS	:	\$	16,988.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 8938 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
41 LED WITH HEAT SINK <i>new</i>	1	\$	733.00	+
42 CONTROL UNIT FOR LIGHT CONTROL SYST. <i>MP</i>	1	\$	557.00	+
43 HEADLIGHT HOSE - RH <i>new</i>	1	\$	40.00	+
44 HEADLIGHT WASHER CYLINDER - LH/RH <i>new</i>	2	\$	284.00	+
45 HEADLIGHT WASHER HOSE <i>new</i>	1	\$	68.00	+
46 WASH WATER RESERVOIR <i>new</i>	1	\$	206.00	+
47 FRONT LOCK CARRIER <i>Dishled</i>	1	\$	727.00	✓
48 COOLANT <i>new</i>	1	\$	179.00	✓
49 A/C CONDENSER ?	1	\$	529.00	?
50 REFRIGERANT LINE (CONDENSER->CUT OFF POINT)	1	\$	519.00	+
51 REFRIGERANT LINE (COMPRESSOR->CONDENSER)	1	\$	475.00	+
52 AIR COND PIPE BEACKET	1	\$	19.00	+
53 ADDITIONAL RADIATOR ?	1	\$	859.00	?
54 RADIATOR ?	1	\$	951.00	?
55 RADIATOR BUSH - LOWER ?	2	\$	19.00	?
56 RADIATOR BRACKET - UPPER ?	2	\$	82.00	?
57 RADIATOR SEALING STRIP - LH/RH ?	2	\$	32.00	?
58 RADIATOR FAN WITH FAN RING ?	1	\$	1,265.00	?
59 RADIATOR AIR GUIDE - LH/RH ?	2	\$	50.00	?
60 RADIATOR SEAL - RH OUTER ?	1	\$	8.00	?
SUB TOTAL SPARE PARTS	:	\$	7,602.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 8938 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
61 RADIATOR AIR GUIDE - UPPER CENTRE ?	1	\$	12.00	?
62 INTAKE AIR DUCT COVER ?	1	\$	29.00	?
63 INTAKE AIR GUIDE - LOWER ?	1	\$	56.00	?
64 INTAKE AIR GUIDE - INNER ?	1	\$	20.00	?
65 INTAKE AIR GUIDE HOSE <i>new</i>	1	\$	34.00	+
66 WATER DRAINAGE HOSE <i>new</i>	1	\$	33.00	+
67 INTAKE CONNECTION <i>new</i>	1	\$	610.00	+
68 INTAKE CONNECTION SEAL <i>new</i>	1	\$	14.00	+
69 CHARGE AIR COOLER <i>new</i>	1	\$	775.00	+
70 FRONT NO. PLATE <i>Dented</i>	S/N	\$	60.00	✓
71 SUNDRIES ?		\$	350.00	?
TOTAL SPARE PARTS	:	\$	35,841.00	
TOTAL LABOUR CHARGES	:	\$	12,444.00	
GRAND TOTAL	:	\$	48,285.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Cj*
SURVEYED DATE : *28/01/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 09 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT