

Car-in

29/1/21.

cip 13224

Kiam/Hong

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Adrian

Veron.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 8938 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 FRONT BUMPER <i>Disfated</i>	1	\$	1,987.00	✓
2 FRONT BUMPER FIXING PARTS <i>Ne m</i>	1	\$	187.00	+
3 FRONT BUMPER GUIDE - LH/RH <i>Ne m</i>	2	\$	78.00	+
4 FRONT BUMPER GRILLE - LOWER <i>amb</i>	1	\$	160.00	✓
5 FRONT BUMPER CLOSING ELEMENT - LOWER <i>amb</i>	1	\$	536.00	+
6 FRONT BUMPER CLOSING ELEMENT - LH/RH <i>amb</i>	2	\$	594.00	297.
7 FRONT BUMPER COVER TRIM - LH/RH <i>Ne m</i>	2	\$	326.00	+
8 FRONT BUMPER ADAPTER - LH/RH <i>Ne m</i>	2	\$	76.00	+
9 RADIATOR GRILLE <i>amb</i>	1	\$	1,406.00	✓
10 RADIATOR GRILLE CLOSING ELEMENT <i>amb</i>	1	\$	191.00	✓
11 FRONT BUMPER AIR GRILLE - LH/RH <i>amb</i>	2	\$	376.00	188.
12 FRONT REINFORCEMENT BEAM <i>Be m</i>	1	\$	795.00	2
13 FRONT BUMPER FOAM FILLER <i>amb</i>	1	\$	189.00	2
14 FRONT BUMPER FOAM COVER <i>amb</i>	1	\$	122.00	✓
15 STICKER FOR AIR CONDITIONER <i>gala</i>	1	\$	8.00	✓
16 SIGN 'CAUTION' STICKER	1	\$	14.00	✓
17 SIGNAL HORN - LH/RH	2	\$	400.00	?
18 FRONT FENDER - LH/RH <i>RH Rys, LH Rys</i>	2	\$	1,702.00	+
19 FRONT FENDER ATTACHMENT PARTS <i>Ne m</i>	1	\$	72.00	+
20 FRONT FENDER BRACKET - RH FRT <i>Ne m</i>	1	\$	39.00	+
SUB TOTAL SPARE PARTS	:	\$	9,258.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 8938 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 FRONT FENDER BRACKET - RH REAR	1	\$	28.00	+
22 FRONT FENDER BRACE - RH	1	\$	96.00	+
23 FRONT FENDER POP RIVET	10	\$	33.00	+
24 FRONT WHEEL HOUSING LINER - LH/RH	2	\$	338.00	+
25 WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$	89.00	+
26 BONNET <i>Dented</i>	1	\$	3,134.00	✓
27 BONNET ATTACHMENT PARTS <i>Ne m</i>	1	\$	165.00	+
28 BONNET HINGE - LH/RH <i>Bent</i>	2	\$	124.00	✓
29 BONNET CATCH HOOK <i>Ne m Bent</i>	1	\$	90.00	✓
30 BONNET LOCK STRIKER - LH/RH <i>Bent</i>	2	\$	220.00	✓
31 BONNET EDGE PROTECTION <i>Ne m</i>	1	\$	28.00	✓
32 BONNET LOCK - LH/RH <i>Damaged</i>	2	\$	427.00	✓
33 BONNET HINGE COVER - LH/RH <i>Ne m</i>	2	\$	8.00	+
34 BONNET BOWDEN CABLE <i>Tampered</i>	1	\$	58.00	✓
35 BONNET LOCK CABLE <i>Ne m ?</i>	1	\$	74.00	?
36 BONNET BOWDEN CABLE COVER <i>?</i>	1	\$	10.00	?
37 BONNET SOUND ABSORBER <i>Ne m</i>	1	\$	219.00	+
38 PLENUM CHAMBER COVER <i>Ne m</i>	1	\$	179.00	+
39 LED HEADLIGHT - LH/RH <i>LH cracked, RH bent</i>	2	\$	10,910.00	✓
40 MAIN LIGHT POWER MODULE <i>Ne m</i>	1	\$	758.00	+
SUB TOTAL SPARE PARTS	:	\$	16,988.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 8938 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
41 LED WITH HEAT SINK <i>new</i>	1	\$	733.00	+
42 CONTROL UNIT FOR LIGHT CONTROL SYST. <i>HP</i>	1	\$	557.00	+
43 HEADLIGHT HOSE - RH <i>new</i>	1	\$	40.00	+
44 HEADLIGHT WASHER CYLINDER - LH/RH <i>new</i>	2	\$	284.00	+
45 HEADLIGHT WASHER HOSE <i>new</i>	1	\$	68.00	+
46 WASH WATER RESERVOIR <i>new</i>	1	\$	206.00	+
47 FRONT LOCK CARRIER <i>Dislod</i>	1	\$	727.00	✓
48 COOLANT <i>new</i>	1	\$	179.00	✓
49 A/C CONDENSER <i>Bent</i>	1	\$	529.00	✓
50 REFRIGERANT LINE (CONDENSER->CUT OFF POINT)	1	\$	519.00	+
51 REFRIGERANT LINE (COMPRESSOR->CONDENSER)	1	\$	475.00	+
52 AIR COND PIPE BEACKET	1	\$	19.00	+
53 ADDITIONAL RADIATOR <i>Bent</i>	1	\$	859.00	✓
54 RADIATOR <i>Bent</i>	1	\$	951.00	✓
55 RADIATOR BUSH - LOWER	2	\$	19.00	?
56 RADIATOR BRACKET - UPPER <i>could</i>	2	\$	82.00	✓
57 RADIATOR SEALING STRIP - LH/RH	2	\$	32.00	?
58 RADIATOR FAN WITH FAN RING	1	\$	1,265.00	?
59 RADIATOR AIR GUIDE - LH/RH <i>could</i>	2	\$	50.00	✓
60 RADIATOR SEAL - RH OUTER <i>new</i>	1	\$	8.00	✓
SUB TOTAL SPARE PARTS	:	\$	7,602.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 8938 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
61 RADIATOR AIR GUIDE - UPPER CENTRE ?	1	\$	12.00	?
62 INTAKE AIR DUCT COVER ?	1	\$	29.00	?
63 INTAKE AIR GUIDE - LOWER ?	1	\$	56.00	?
64 INTAKE AIR GUIDE - INNER ?	1	\$	20.00	?
65 INTAKE AIR GUIDE HOSE <i>new</i>	1	\$	34.00	+
66 WATER DRAINAGE HOSE <i>new</i>	1	\$	33.00	+
67 INTAKE CONNECTION <i>new</i>	1	\$	610.00	+
68 INTAKE CONNECTION SEAL <i>new</i>	1	\$	14.00	+
69 CHARGE AIR COOLER <i>new</i>	1	\$	775.00	+
70 FRONT NO. PLATE <i>Dented</i>	S/N	\$	60.00	✓
71 SUNDRIES ?		\$	350.00	?
TOTAL SPARE PARTS	:	\$	35,841.00	
TOTAL LABOUR CHARGES	:	\$	12,444.00	
GRAND TOTAL	:	\$	48,285.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.