

# HUI HUANG HONG BAO MOTORS

2 Kaki Bukit Ave 2 #02-11 Kaki Bukit AutoHub Singapore 417921

Tel : 6844 7414 Fax : 6844 7401 Email : alisonhbbb@gmail.com

M/s Popular Rent A Car Pte Ltd  
501 Guillemard Road  
Singapore 399840

TPLonPac.  
Denise

Date of survey: 29 Januar

Surveyor: Adrian Ling

29th September 2021

GPT1121378

Type of repair: **Lump Sum**

**Estimate cost of repairs to Honda Shuttle Hybrid - SLX 2292 S**

1 pc	Tailgate <i>Delhid</i>	\$ 1,193.40	✓
1 pc	Tailgate 'H' emblem <i>xc</i>	\$ 33.10	✓
1 pc	Tailgate 'Hybrid' emblem <i>green</i>	\$ 65.20	✓
1 pc	Tailgate 'Shuttle' emblem	\$ 55.00	✓
1 pc	Tailgate moulding <i>new</i>	\$ 95.10	x
1 pc	Tailgate weatherstrip <i>new</i>	\$ 95.10	+
1 pc	Tailgate inner lock <i>Dead</i>	\$ 175.10	✓
1 pc	Tailgate inner trim board <i>crackd</i>	\$ 619.50	366.50
1 pc	RH tailgate reflector <i>at</i>	\$ 380.90	✓
1 pc	RH rear lamp <i>lt</i>	\$ 520.50	✓
1 pc	Rear windscreen lower moulding <i>green</i>	\$ 80.00	✓
1 pc	Rear windscreen top moulding	\$ 30.10	✓
1 pc	Rear end panel <i>Delhid</i>	\$ 601.50	✓
1 pc	Rear end panel centre garnish <i>Delhid</i>	\$ 155.60	✓
1 pc	Rear bumper <i>Delhid</i>	\$ 1,150.60	972
2 pcs	Rear bumper retainers @S\$28.60 <i>xc</i>	\$ 57.20	✓
		\$ 5,307.90	
	Less 20%	\$ 1,061.58	
		\$ 4,246.32	

4686.10  
Less 20% : 3748.88

1 set	Tailgate inner trim clips <i>new</i>	\$ 20.00	✓
1 set	Rear bumper clips <i>new</i>	\$ 25.00	✓
1 pc	Rear windscreen sealant <i>new</i>	\$ 40.00	✓
1 set	Reverse sensors <i>Days</i>	\$ 250.00	✓
	To remove and refit rear windscreen glass	\$ 150.00	120
	To remove and refit reverse sensors	\$ 60.00	40
	To remove and refit tailgate interior fittings	\$ 120.00	80
	To remove and refit back-up camera	\$ 50.00	✓
	Labour charges to remove, adjust and renew the above parts etc	\$ 800.00	700
	Tuff kote	\$ 60.00	✓
	Wiring charges	\$ 50.00	✓
	Spray painting	\$ 800.00	700
		\$ 6,671.32	

285

1800

LKK Auto Consultants hereby certify that the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Written" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Dollars : Six thousand six hundred seventy-one dollars and thirty-two cents

Supplementary : 350  
total : 6223.88  
Lump Sum : 4950

Adrian Ling 96893735  
29/01/21 H/s 06 Days.

# HUI HUANG HONG BAO MOTORS

2 Kaki Bukit Ave 2 #02-11 Kaki Bukit AutoHub Singapore 417921  
Tel : 6844 7414 Fax : 6844 7401 Email : alisonhbbb@gmail.com

M/s Popular Rent A Car Pte Ltd  
501 Guillemard Road  
Singapore 399840

Date of survey: 29 January 21  
Surveyor: Adrian Ling

29th September 2021

Type of repair: Lump Sum

## Supplementary cost of repairs to Honda Shuttle Hybrid - SLX 2292 S

1 pc	Reverse Camera	Damaged	\$ 350.00	SN	✓
	To remove and refit reverse camera		<del>\$ 60.00</del>		40.
			<u>\$ 410.00</u>		

Dollars: Four hundred ten dollars

Supplementary: 390