

# HUI HUANG HONG BAO MOTORS

2 Kaki Bukit Ave 2 #02-11 Kaki Bukit AutoHub Singapore 417921

Tel : 6844 7414 Fax : 6844 7401 Email : alisonhbbb@gmail.com

M/s Popular Rent A Car Pte Ltd  
501 Guillemard Road  
Singapore 399840

Date of survey: 29 January 21  
Surveyor: Adrian Ling

29th September 2021

Type of repair: Lump Sum

## Supplementary cost of repairs to Honda Shuttle Hybrid - SLX 2292 S

1 pc	Reverse Camera	Damaged	\$ 350.00	SN ✓
	To remove and refit reverse camera		<del>\$ 60.00</del>	40.
			<u>\$ 410.00</u>	

Dollars: Four hundred ten dollars

Supplementary: 390