

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMW7659D/2101007

28th January 2021

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not added
A/P
The 1st Attorney
2 Lys.
4/2/21

Date of Accident : 26th January 2021
Location : Kim Keat palm market
Third Party Claim Vehicle No : GBK 5135 E
Repair Cost For Vehicle No : SMW 7659 D Mercedes A200

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Headlamp assy LH <i>one ✓ 3044.61</i>	1	3,392.00	\$ 3,392.00 ✓
2	Headlamp lower bracket LH <i>RuX</i>	1	702.00	\$ 702.00 X
3	Front bumper fascia <i>n X</i>	1	1,617.00	\$ 1,617.00 X
4	Front bumper clips <i>n 1 X</i>	1set	65.00	\$ 65.00 X
5	Front bumper side retainer LH <i>n 1 X</i>	1	84.00	\$ 84.00 X
6	Front bumper fog lamp cover LH <i>n 1 X</i>	1	123.00	\$ 123.00 X
7	Front grille rivet <i>rec ?</i>	15pcs	6.00	\$ 90.00 X
				\$ 6,073.00

Labour Charges :-

	Amounts
Cut out, renew, knocking & welding front support panel, remove & install all damage parts & re-align body	\$ 780.00 <i>200</i>
Spray painting on damage parts	\$ 780.00 <i>200</i>
Check all lighting after repairs	\$ 35.00 <i>100</i>
Diagnostic & reset	\$ 300.00

Labour Charge	\$ 1,895.00
Total Amount	\$ 7,968.00

GST will be reflected in the final bills.