SKL 7634G

PARTS

S/N

\$225.43 \$199.80 \$105.00 \$148.22 \$615.00 \$255.00 \$50.00 \$2,277.75 \$92.50 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$5,045.15 \$5,045.15 95% \$4,792.89 \$0.00 \$0.00 \$0.00 \$0.00

> \$0.00 \$0.00 \$0.00 \$0.00 \$0.00

\$1,076.45

	70.00			
	\$0.00			
	\$0.00			
	\$0.00			
	\$0.00			
	\$0.00			
	\$0.00			
	\$0.00			
	φ0.00			
LADOUD				
LABOUR	ć20.00			
	\$30.00			
	\$60.00			
	\$50.00			
	\$300.00			
	\$400.00			
	\$0.00			
	\$0.00			
	\$0.00			
	\$0.00			
	\$0.00			
	\$0.00			
	\$0.00			
	\$0.00			
	\$0.00			
	\$0.00			
	\$0.00			
	\$840.00			
	70 10.00			
TOTAL				
101712	\$4,792.89			
	\$0.00			
D/D	\$840.00			
P/P	\$5,632.89			
1./C	ćE (22.00			
L/S	\$5,632.89			
	80%			
	\$4,506.31			
=	\$4,500.00	RED	\$4,940.42	52%
REPAIR DAYS	<u>3</u>	TOTAL TP EST	\$9,440.42	
	A			
MARKET VALUE	\$59,000.00			
LTA REBATE	\$47,505.00			
NETT VALUE	\$11,495.00			
	VOLKSWAGEN			
MAKE / MODEL	GOLF (1984cc)			

\$0.00