

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

WHEELS EXPRESS RENTAL & LEASING PTE LTD
 2 SIMS CLOSE #01-08
 SINGAPORE 387298

*TP AXA
 Cecilia.*

Contact : 90603343, 94521429

ESTIMATE

Repair Code : CLM16680
 Date in : 28/01/2021
 Vehicle Num. : SKC4712G
 Model : HONDA JAZZ 1.4A
 Chassis/Eng# : JHMGD18507S221503/L13A54001558

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Deformed.</i>	1	650.00	<i>485</i> 650.00
REAR BUMPER SIDE RETAINER L/R <i>Nec</i>	2	24.50	49.00
REAR END PANEL <i>Dented.</i>	1	415.00	415.00
REAR END PANEL INNER TOP GARNISH <i>Deformed.</i>	1	105.00	105.00
REAR FENDER INNER TRIM BOARD COVER L/R <i>Cracked.</i>	2	250.00	500.00
REAR FLOOR PANEL TOP BOARD COVER <i>Deformed</i>	1	289.80	289.80
REAR TAILGATE <i>Repair</i>	1	874.90	X 874.90
REAR TAILGATE 'JAZZ' EMBLEM <i>Nec</i>	1	45.00	45.00
REAR TAILGATE INNER PULL GARNISH <i>NEM</i>	1	15.00	X 15.00
REAR TAILGATE INNER RUBBER STOPPER L/R <i>NEM</i>	2	11.80	X 23.60
REAR TAILGATE INNER TRIM BOARD <i>NEM</i>	1	135.00	X 135.00
REAR TAILGATE MECHANISM LOCK <i>NEM</i>	1	232.10	X 232.10
REAR TAILGATE WEATHER STRIP <i>Wt</i>	1	138.40	138.40
REAR TAILGATE WINDSCREEN MOULDING (TOP & LOWER) <i>NEM</i>	2	78.00	X 156.00
REAR TAILLAMP INNER RUBBER GASKET L/R <i>Nec</i>	2	30.00	40 60.00
REAR TAILLAMP L/R <i>Cracked.</i>	2	380.00	590 760.00
REAR TAILLAMP LOWER BRACKET L/R <i>Bent</i>	2	25.00	50.00

*2707.20
 2165.76*

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

WHEELS EXPRESS RENTAL & LEASING PTE LTD
 2 SIMS CLOSE #01-08
 SINGAPORE 387298

Contact : 90603343, 94521429

ESTIMATE

Repair Code : CLM16680
 Date in : 28/01/2021
 Vehicle Num. : SKC4712G
 Model : HONDA JAZZ 1.4A
 Chassis/Eng# : JHMGD18507S221503/L13A54001558

		Subtotal before discount	4,498.80
	Percentage discount 20%		899.76
		Sub-total 1	3,599.04
REAR BUMPER CLIPS - SET <i>Neu</i>	1	50.00	<i>30</i> 50.00
REAR BUMPER REVERSE SENSOR - SET <i>Damaged</i>	1	250.00	<i>200</i> 250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>Neu</i>	1	30.00	<i>10</i> 30.00
REAR FENDER INNER TRIM BOARD COVER CLIPS L/R - SET <i>Neu</i>	2	50.00	<i>60</i> 100.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>Neu</i>	1	50.00	<i>X</i> 50.00
REAR TAILGATE WINDSCREEN SEALANT <i>Neu</i>	1	80.00	<i>320</i> X 80.00
REAR TAILLAMP CLIPS L/R - SET <i>Neu</i>	2	25.00	<i>20</i> 50.00
		Subtotal before discount	610.00
	Percentage discount 0%		0.00
		Sub-total 2	610.00
		Parts-total	4,209.04

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	<i>✓</i>	60.00
To remove, reinstall tailgate windscreen	<i>X</i>	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	<i>60</i>	120.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	<i>80</i>	1,200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	<i>650</i>	1,200.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

WHEELS EXPRESS RENTAL & LEASING PTE LTD
 2 SIMS CLOSE #01-08
 SINGAPORE 387298

Contact : 90603343, 94521429

ESTIMATE

Repair Code : CLM16680
 Date in : 28/01/2021
 Vehicle Num. : SKC4712G
 Model : HONDA JAZZ 1.4A
 Chassis/Eng# : JHMGD18507S221503/L13A54001558

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

	1830	60 100.00
		X 80.00
Labour Total		2,910.00
Parts & Labour Total		7,119.04

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total: 4115.764
 H/S: 3.3K (Nett Value)
 Nett: 28K
 05 Days
 3.3K