



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
CHEN YOUSHENG	Cust No/Name	/CHEN YOUSHENG
640 WOODLANDS RING ROAD	Reg No/Reg Date	SMV9968D / 09/09/202
#08-09	Date In/Mileage	/ 0
SINGAPORE 730640	Chassis No	JMAXTGK1WLZ001702
Contact No Mobile: 91928868	Engine No	4B40HM5805
	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C STYLE (T3
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	28/01/2021/ 18:33		442 / CocoLu	62395

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, FRT FENDER LH, 450X2				900.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH 350X2				700.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				60.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY Sundry				20.00
M SUNDRY MOULDING, FR WHEEL ARCH LH -- 7400A671				
M SUNDRY HEADLAMP --- 8301D693				
M FACE, FR BUMPER	1.00	704.00	00.00	704.00
M BRKT, F/BMPR T/SIG LAMP, LH	1.00	17.00	00.00	17.00
M GARNISH, FR BUMPER SIDE	1.00	214.00	00.00	214.00
M BRACKET, FR BUMPER SIDE, LH	1.00	18.00	00.00	18.00
M INSULATOR, FR FENDER, LH	1.00	52.00	00.00	52.00
M FENDER, FR LH	1.00	599.00	00.00	599.00
M SHIELD, FR WHEELHOUSE, LH	1.00	135.00	00.00	135.00
M PNL, HEADLAMP SUPT, UPR LH	1.00	59.00	00.00	59.00
M LAMP A, T/SIG & FOG, FR LH	1.00	506.00	00.00	506.00

Estimate

CUT (no price) - \$1120.00 ✓
 BR ? x MM
 MIS
 MIS (no price)
 Steve (LKK)
 DD-MM AL
 EXARS-?
 PIP
 My Bel SM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during repair

Confirm & accepted by

- No illegal modification(s) is allowed
- Supplementary Item(s) must be approved and is subject to final approval from the repairer company

Acknowledged by Repairer

Authorized signatory and company stamp

29/1/21, 10.00am
4 days

Nett	4,134.00
7% GST on	289.38
Total Payable	4,423.38

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.