



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 27.01.2021
Emailed : 18.02.2021, 11.30am
Date Survey : 29.01.2021

VEHICLE NO : SMV 9968 D
MODEL : MIT ECLIPSE CROSS 1.5
WIP : 62395

Table with 2 columns: Description and Amount. Rows include Material (\$2,504.04), Labour (\$2,180.00), Sub-Total (\$4,684.04), Less Excess (\$800.00), Total (\$3,884.04), GST 7% (\$271.88), Grand Total (\$4,155.92), and Finalise By/Date (LOI / 18/02/2021).

[X] REVERT BACK WITHIN 7 DAYS, OTHERWISE WILL PROCEED WITH INVOICING

[ ] SURVEYOR'S REPORT REQUIRED

[ ] REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends + 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

[ ] TP claim

[ ] Claim GIA / LTA fee

[ ] Claim Loss of [ ] Use / [ ] Rental

[ ] Claim Medical Fee / Others

[ ] Third Party Report -



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892  29/01/2021	Cust No/Name	/CHEN YOUSHENG
	Reg No/Reg Date	SMV9968D / 09/09/2020
	Date In/Mileage	29/01/2021/ 2000
	Chassis/Package	JMAXTGK1WLZ001702 /#
	Engine No	4B40HM5805
	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C STYLE (T31)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	18/02/2021/ 09:40	BLC	260 / AiTing	62395

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, LH FRONT FENDER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 900.00
E PNT98000 RESPRAY ON FRONT BUMPER, LH FRONT FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 700.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR TO FACILITATE REPAIR				✓ 60.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE				✓ 120.00
M SUNDRY SUNDRIES				✓ 20.00
X EXC EXCESS FOR OWN DAMAGE CLAIM				-800.00
E PNT98000 RESPRAY ON BONNET → Supp				350.00
X FACE,FR BUMPER	1.00	✓ 704.00	23.00	542.08
X GARNISH,FR BUMPER SIDE	1.00	✓ 214.00	23.00	164.78
X BRACKET,FR BUMPER SIDE,LH	1.00	✓ 18.00	23.00	13.86
X FENDER,FR LH	1.00	✓ 599.00	23.00	461.23
X LAMP A,T/SIG & FOG,FR LH	1.00	✓ 506.00	23.00	389.62
X MOULDING,FR WHEEL ARCH,LH → Supp	1.00	151.00	23.00	116.27
X HEADLAMP ASSY,LH	1.00	✓ 1020.00	23.00	785.40
X CLIP → Supp	20.00	2.00	23.00	30.80
Z TEXT AIG OD CLAIM DOA : 27.01.21 SURVEYOR STEVE LKK 29.01.21 POLICY NO : 2070119602				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	2,504.04		Nett	3,884.04
Labour	2,160.00	7% GST on	3884.04	271.88
Standard Menu	0.00			
Specialist Job	0.00			
Diagnostics Job	0.00		Total Payable	4,155.92
Sundry/Others	-780.00			
Total(w/o GST)	3,884.04			

This is not an official tax invoice.  
This is a computer generated document, no signature is required.



# Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SMV 9968 D

## Materials

## Cost (\$)

1	Moulding, Fr wheel arch, LH	151.00	✓ nec
2	Clips (x20)	40.00	✓ nec

Total	191.00
Less 23%	43.93

Total Materials	147.07
-----------------	--------

## Labour

## Cost (\$)

1	Respray on bonnet	350.00	✓
---	-------------------	--------	---

Total Labour	350.00
--------------	--------

Taxable Amount	497.07
7% GST	34.79

<b>Grand total</b>	<b>531.86</b>
--------------------	---------------

Thank You.

Yours faithfully  
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

  
LOI AI TING  
SENIOR OFFICER - ADMIN  
TEL: 6568 4556 / 6568 4501

All DTCs

2021.02.10

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	GK1W 2020MY

SMV 99685.

SMUT. IV Diag. chk.

↳ Read & Clear DTC.

After

All DTCs

2021.02.10

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_OC640000		No DTCs	
AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs	
4WS/Electric Power Steering	EPS_45840000		No DTCs	
ABS/ASC/ASTC/WSS	ASC_42080014		No DTCs	
SRS-AIR BAG	SRS_81047305		No DTCs	
Air Conditioner	AC_80080017		No DTCs	
ETACS	ETACS_83040800		No DTCs	
TPMS (with KOS)	ETACS_83040800		No DTCs	
Meter	METER_84088001		No DTCs	
Steering Angle Sensor	GS_SAS_47000100_ForumMUT3		No DTCs	
AUDIO (IntelligentDisplay)	AUDIO_8D080002		No DTCs	
LIN	ETACS_83040800		Non-target System	
KOS/OSS/IMMO/Keyless (with KOS)	ETACS_83040800		No DTCs	

All DTCs

2021.02.10

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
CORNER SENSOR/SONAR	SONAR_9D080000		No DTCs	
ACC/FCM	ACCSFCM_4B080004		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCs	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		No DTCs	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	
HUD	HUD_9E080000		Non-equipped System or Communication Error	