



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

GAI Insured's Veh No : XE117L

Date of Accident : 22 January 2021

Messrs Mopi Pte Ltd

Date : 23 January 2021

Estimate To Repair GBC1321C - Toyota DYNA 150 MANUAL 3SEATER

Chassis No : JTFAT35Y10K201526

Uke
Per: 29/01/2021 C1630u

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper	645.01 ← \$ 700.00
02	1 pc	n/s headlamp	681.20 ← \$ 1,050.00
03	1 pc	n/s headlamp lower garnish	\$ 78.00
04	1 pc	n/s headlamp bracket	\$ 65.00
05	1 pc	front body panel	1150 ← \$ 1,195.00
06	1 pc	front body panel "Dyna" badge	\$ 63.90
07	1 pc	front body panel side garnish n/s -black	\$ 55.00
08	1 pc	front body panel top garnish - black	\$ 35.00
09	1 pc	blower motor assy	\$ 2,265.00
10	1 pc	n/s side mirror stay assy	\$ 815.00 ← \$ 815 135.00
		Less 25 %	\$ 5,641.90
			\$ 1,410.48
			\$ 4,231.42
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 80.00
02		To rust-proofing of the affected areas.	\$ 80.00
03		To dismantle and refit instrument dashboard, check electrical lightings and re-run, re-route wire harness.	\$ 250.00
04		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 200.00
05		To remove and refit front windscreen glass.	\$ 120.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00
07		Putty and spray painting of the affected portion.	\$ 800.00
			\$ 2,330.00
		Total	\$ 6,561.43

Tan Lim 97495749

WP 29/1/21 @ 430pm

1/3 Resing after repair

tanlim@lkkant.com

05-06 days

bt
Zm
X NN
bt
ner
mis
nd
X NN
bt
30
30
180? plus
100? plus
? /
600
600
1560

Policy No : 8-V0004831-MVA-R008
Date of Accident : 22 January 2021



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Claims Department
QBE Insurance (Singapore) Pte Ltd
1 Raffles Quay #29-10
South Tower
Singapore 048583

Date : 02 February 2021

Supplementary To Repair GBC1321C - Toyota DYNA 150 MANUAL 3SEATER
Chassis No : JTFAT35Y10K201526

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front grille	\$ 550.00
02	1 pc	front grille top seal	\$ 30.00
03	1 pc	chassis crossmember bumper bracket LH	\$ 190.00
		Less 25 %	\$ 770.00
			\$ 192.50
		Total	\$ 577.50
			\$ 577.50

again
2/2/21
1350.

2583.83.

1560

483.07

4626.90

4583700

Galays.

644.10
483.07.