

ASS. REC. BY: Tan LinREF: CS/CT/21001385/Ttd3.

ASSIGNMENT

CoE 2021 May

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: XE117LPolicy No. DMCVSNA00012072100Claims No. SNM21D200536/C02/TANKL

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 98K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBC1321C Yr Regn: 2011 MayType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Dyna C.C. 2982Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 438000 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT35810K201526

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim orTyre Size: F: 195/R15R: 155/R12 (D)BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6/6 mmL/Bal. 6 mm L/Bal. 6/6 mmD.O.A. _____ D.O.I. 29/1/21Survey held at Tan Lim MotorDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

COR I/s\$3700, 6 days.

(RED: 3438.93; 48%)

7138.93

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☒ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.B.A. / 3700

Days Of Repair: 6Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

GAI Insured's Veh No : XE117L
Date of Accident : 22 January 2021

Messrs Mopi Pte Ltd

Date : 23 January 2021

Estimate To Repair GBC1321C - Toyota DYNA 150 MANUAL 3SEATER
Chassis No : JTFAT35Y10K201526

U66
Rev: 29/01/2021 1630h

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper	\$ 700.00
02	1 pc	n/s headlamp	\$ 1,050.00
03	1 pc	n/s headlamp lower garnish	\$ 78.00
04	1 pc	n/s headlamp bracket	\$ 65.00
05	1 pc	front body panel	\$ 1,195.00
06	1 pc	front body panel "Dyna" badge	\$ 63.90
07	1 pc	front body panel side garnish n/s -black	\$ 55.00
08	1 pc	front body panel top garnish - black	\$ 35.00
09	1 pc	blower motor assy	\$ 2,265.00
10	1 pc	n/s side mirror stay	\$ 135.00
		Less 25 %	\$ 5,641.90
			\$ 1,410.48
			\$ 4,231.42
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 80.00
02		To rust-proofing of the affected areas.	\$ 80.00
03		To dismantle and refit instrument dashboard, check electrical lightings and re-run, re-route wire harness.	\$ 250.00
04		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 200.00
05		To remove and refit front windscreen glass.	\$ 120.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00
07		Putty and spray painting of the affected portion.	\$ 800.00
			\$ 2,330.00
		Total	\$ 6,561.43

Tanfan 97495749
WP 29/1/21 18430pm
1/3 Resurvey after repair
tanfan@lkkauto.com
05-06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Non-legal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: