

ASS. REC. BY: Sun Pin

REF:

NTUC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMB 1061 Yr Regn: 07/10/2008Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes benz OC500 c.c. 11967Colour: Black. A/C: Insured / Std / NI / NASp. Reading: 981661 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WEB63442021000667Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 275 / 70 R 22.5R: 275 / 70 R 22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 28/01/2024Survey held at SMRTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Pending Workshop GIA

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / B.B. (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL



SMRT Accident Vehicle Repair Estimates

| |
|---|
| SMRT Automotive Services Pte Ltd |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592 |
| Estimator Telephone Number : 68662623 |
| Accident Reporting Number : 68662672 |

Date Generated : 28/01/2021


User ID : BoonChewTay

Section A - Accident Details

| | |
|------------------------------------|--|
| Registration Number | SMB10G |
| Case Reference Number | BUS/01/21/1041 |
| Registration Date | 7/10/2008 |
| Company Type | SMRT Buses Ltd |
| Make | MERCEDES |
| Model | MBOC500 |
| Name of Driver | Teyu Soin Boon |
| Type of Accident | Head to Rear |
| Accident Date and Time | 22/1/2021 2:49 PM |
| Accident Reported Date and Time | 22/1/2021 3:15 PM |
| Is Surveyor Required? | No |
| Survey by | |
| Vehicle is Towed Back? | No |
| Towed Back Date and Time | |
| Replacement Vehicle issued? | No |
| Job Card Number | |
| Special Instruction to ARC, if any | SMB10G - REAR RIGHT PORTION SMA4342C (TP) - INSURED WITH NTUC |
| Prepared Date and Time | 28/1/2021 2:17 PM |
| Chassis Number | WEB63442021000067 |
| Mileage | |
| Work Shop | |
| Repair Completion Date and Time | |

Section B - Summary of Repair Estimates

Summary of Repair Estimates

| | Quotation from ARC | Adjusted by Surveyor, if applicable |
|------------------------------|---|-------------------------------------|
| Total Labour Cost | \$1,590.00 | \$0.00 |
| Total Spray Cost | \$602.00 | \$0.00 |
| Total Spare Part Cost | \$2,359.60 | \$0.00 |
| Total Other Cost | \$0.00 | \$0.00 |
| TOTAL COST | \$4,551.60 | \$0.00 |
| Lump Sum Total | \$4,550.00 | \$0.00 |
| Number of Repair Days | 4.0 | |
| Prepared / Adjusted By | ARC Manager Team | |
| ARC / Surveyor Sign Off Date | 28/01/2021 2:33 PM | |
| Signature |  | <input checked="" type="checkbox"/> |
| Remarks | | |

Section C - Quotation and Accident Invoice Details

| | | | |
|------------------|--|----------------|--|
| Quotation Number | | Invoice Number | |
| Quotation Date | | Invoice Date | |
| Invoice Amount | | Prepared Date | |



SMRT Accident Vehicle Repair Estimates

| |
|---|
| SMRT Automotive Services Pte Ltd |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592 |
| Estimator Telephone Number : 68662623 |
| Accident Reporting Number : 68662672 |

Date Generated : 28/01/2021

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. | \$1,590.00 | 1060 |
| Total Labour | \$1,590.00 | |

Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS | \$602.00 | 432 |
| Total Spray Painting & Panel Beating | \$602.00 | |

Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------|--------------------|-------------------------------------|
| Total Other Costs | | |

Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|--|----------|-----------------|--------------|------------------|--------------------|-------------------|
| 009367 | Body | 6013 | DOOR, REAR, ENGINE, F OR MB OC500 BUS | 1.00 | \$2,484.00 | 100.00 | \$0.00 | Repair | X R. |
| 009366 | Body | | BUMPER, REAR, FIBREGLASS, FOR MB OC500 BUS | 1.00 | \$1,863.00 | 10.00 | \$1,676.70 | Replace | / CRU |
| 009369 | BODY RH | | COVER, LAMP, REAR, RH, FOR MB OC500 BUS | 1.00 | \$1,242.00 | 10.00 | \$1,117.80 | Replace | / CRU |
| | | | STICKER SMRT | 1.00 | \$75.00 | 0.00 | \$75.00 | Replace | / CRU |
| | | | STICKER SG LOVE | 1.00 | \$75.00 | 0.00 | \$75.00 | Replace | / NRC |
| | | | STICKER 60KM/H | 1.00 | \$5.00 | 0.00 | \$5.00 | Replace | / NRC |
| Total | | | | | \$5,744.00 | | \$2,949.50 | | |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| Total | | | | | | | | | |

Repair day - 3 days.

L/S
After paint photo
Sun Pm (L/S)
28/01/2021
TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|-------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 292D |
| Vehicle Details | |
| Vehicle No.: | SMB10G |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 29 Jan 2021 |
| Vehicle Make: | MERCEDES BENZ |
| Vehicle Model: | OC500LE1830H |
| Primary Colour: | Black |
| Manufacturing Year: | 2008 |
| Engine No.: | 45796600138357 |
| Chassis No.: | WEB63442021000067 |
| Maximum Power Output: | - |
| Open Market Value: | \$319,038.00 |
| Original Registration Date: | 07 Oct 2008 |
| First Registration Date: | 07 Oct 2008 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$15,952.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Rebate Amount: | \$0.00 |
| Total Rebate Amount: | \$0.00 |

The information contained herein is correct as at 29 Jan 2021

OK