





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 02/03/2021

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB188C
Case Reference Number	BUS/01/21/1043
Registration Date	24/11/2011
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC530
Name of Driver	TAN KIAN CHYE
Type of Accident	Head To Side
Accident Date and Time	26/1/2021 12:04 AM
Accident Reported Date and Time	26/1/2021 1:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109605
Special Instruction to ARC,if any	SMB188C - LEFT FRONT PORTION SLB3214C (TP) - INSURED WITH NTUC
Prepared Date and Time	28/1/2021 3:32 PM
Chassis Number	WEB62808323122710
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$1,325.00
Total Spray Cost	\$786.00	\$616.00
Total Spare Part Cost	\$5,785.26	\$4,584.06
Total Other Cost	\$0.00	(\$388.20)
TOTAL COST	\$8,691.26	\$6,136.86
Lump Sum Total	\$8,700.00	\$6,150.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	29/01/2021 10:56 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 02/03/2021

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$2,120.00				\$1,325.00 ✓		
Total Labour			\$2,120.00				\$1,325.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$786.00				\$616.00 ✓		
Total Spray Painting & Panel Beating			\$786.00				\$616.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Lump Sum Adjustment by Surveyor			\$0.00				(\$388.20)		
Total Other Costs			\$0.00				(\$388.20)		
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	Replace ✓NEC
6009700	VE		LAMP,BLINKER:FRONT, LEFT,FOR MB OC 500 LE	1.00	\$155.30	10.00	\$139.77	Replace	Not Given X SVC
6009904	Body	6288850526	FLAP:FRONT,CENTRE,F OR MB CITARO O530	1.00	\$1,513.05	10.00	\$1,361.74	Replace	Repair X R
6009902	BODY LH	6288800172	BUMPER:FRONT,LH,FO R MB CITARO O530	1.00	\$1,767.78	10.00	\$1,591.00	Replace	Replace ✓CR4
Total					\$3,511.13		\$3,167.51		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
6009895	GLASS	6286712210	WINDSCREEN:FRONT,F OR MB CITARO O530	1.00	\$3,887.85	10.00	\$3,499.07	Replace	Replace ✓CR4
4006313			PRIMER	1.00	\$80.00	0.00	\$80.00	Replace	Replace ✓Nec
4006315			ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace ✓Nec
6000917			IU BRACKET	1.00	\$35.00	0.00	\$35.00	Replace	Replace ✓Nec
4006314	CONSUMABLE		ADHESIVE:DIRECT GLAZING	10.00	\$37.00	0.00	\$370.00	Replace	Replace ✓Nec
Total					4,119.85		4,064.07		

1,666
4,064.07
1,325
616
7,671.07
- 20%
6,136.86

218
\$6,150
2 days