

Sun Pin (LKK Auto)

From: Elena Tan <admin@mycar.sg>
Sent: Monday, 22 March, 2021 5:17 PM
To: Sun Pin (LKK Auto)
Subject: Re: FW: SMX 2879M

Follow Up Flag: Follow up
Flag Status: Flagged

Categories: Green category

Dear Sunpin,

Please close at the same

Kindly divert all correspondent & disbursements to our new office address @ 60 Jalan Lam Huat, Carros Centre #05-21 S(737869) as we will no longer have access to our old address' mailbox.

Best Regards,
Huiqin
General Manager | Motor Claims Department

My Car Consultant Pte Ltd
M: 8866 8832 | F: 6925 5219
W: Mycar.sg | E: Admin@mycar.sg
60 Jalan Lam Huat, Carros Centre #05-21 S(737869)
UEN No.: 201605878Z
GST Registration No.: 201605878Z

From: "Sun Pin (LKK Auto)" <sunpin@lkkauto.com>
Sent: 3/22/21 11:56 AM
To: "admin@mycar.sg" <admin@mycar.sg>
Subject: FW: SMX 2879M

Hi Hui Qin,

Kindly refer the finalize amount \$4,800. Repair day 4 days. (L/S, before gst).

Please confirm the COR by reply email.

Thank you

Best Regards,
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants
Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)