



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21001401/QKvd3n2	
			Date: 26/03/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBG 3406H	Veh. Inspected	SMX 2879M	
Policy No.	D20MTMC01001208	Coverage (\$)	0.00	
Claim No.	CMTD2100317/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	29/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA NOAH HYBRID	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	ZWR800450295	Colour	BLACK	
Odometer	6966 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/01/2021	Inspection Date	29/01/2021	
Survey held at	60 JALAN LAM HUAT, #05-21			
Repairer	MY CAR CONSULTANT PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	