




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN : TAN JUN HONG			Ref: CS3/ASM21001402/R1qf3e2 Date: 08/02/2021 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 6049X	Veh. Inspected	JRC 6736
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S1M031JG	Excess (\$)	0.00
	Assign From	TAN JUN HONG	Assign Date	29/01/2021
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA	c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	MULTI COLOUR
	Odometer	81396 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	70/90-17	MAXXIS	3 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	80/90-17	MAXXIS	3 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. 			
5. General Information				
	Accident Date	23/01/2021	Inspect Date / Time	29/01/2021 (03:55 PM)
	Survey held at	DYNASTY MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-24 MIDVIEW BUILDING SINGAPORE 659578		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

Report Ref No. CS3/ASM21001402/R1qf3e2

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.