

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua

Date: 09 Dec 2016

Preliminary Advice

Insured Vehicle No : GBC5496E

TP Vehicle No : XB9737D

Make : MITSUBISHI FV517JD2RDEB

Date of Inspection : 08/12/2016

Inspection At : GOLDBELL ENGINEERING PTE LTD

Accident Date : 30/08/2016

Assignment Date : 16/11/2016

Est. Duration of Repair : 6/Days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...Front & Rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,234.24
Revised Amount	:S\$	5,834.60
Check Items (Estimated)	:S\$	1,519.03
Total	:S\$	7,353.63

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :We have not authorized repairs.