



# GOLDBELL ENGINEERING

Industrial Vehicles.  
20,000 Served. And Counting.

*Ashu - UK*  
*Alice*

**GOLDBELL ENGINEERING PTE LTD**

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003983G

DATE : 16/11/2016

TO : SANTE ACCESS SYSTEM PTE LTD

ATTN : MS. JANE

OFFICE / MOBILE : 6863-0345

EMAIL ADDRESS : -

FROM : GOLDBELL ENGINEERING P/L

ATTN : MR WILLIAM GO

OFFICE / MOBILE : 6864-0637 / 9755-7336

FAX NO. : 6863-0425

VEHICLE NO. : XB9737D

MODEL NO. : MITSUBISHI FV517P2RDEB

CHASSIS NO. : FV517PA00423

ENGINE NO. : 6D24364749

REG. DATE : 20/07/2005

REF. NO. : GBE/SVC/SALES-4077/161115

D.O.A. : 30/08/2016

POLICY NO. : -

CLAIM TYPE : TP CLAIM - AXA

WORKSHOP : 10 TUAS AVE 18

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1	MC936936	RADIATOR GRILLE	1	\$ ? 658.15
2	MK488747	FRONT BUMPER	1	\$ <i>bt</i> 1,230.60
3	MC962484	FRONT BUMPER STAY RHS	1	\$ ? 386.51
4	MC937491	FRONT BUMPER STEP	1	\$ <i>cut</i> 190.12
5	MC937493	FRONT BUMPER SIDE GARNISH RHS	1	\$ <i>bt</i> 178.45
6	MC966653	FRONT BUMPER CENTRE GARNISH RHS	1	\$ ? 158.52
7	MK677299	FOGLAMP BEZEL RHS	1	\$ <i>cut</i> 64.55
8	MC932209	HEADLAMP RHS	1	\$ ? 514.19
9	MC938091	HEADLAMP BEZEL RHS	1	\$ ? 308.00
10	MK614244	FRONT STEP GARNISH UPPER RHS	1	\$ <i>cut</i> 291.41
11	MK676242	FRONT STEP GARNISH WALL RHS	1	\$ x 275.13
12	MC937839	FRONT STEP GARNISH LOWER RHS	1	\$ x 276.08
13	MC937837	FRONT STEP GARNISH LOWER COVER RHS	1	\$ x 229.87
14	MC937840	FRONT STEP PANEL RHS	1	\$ x 326.60
15	MC147413	TAIL LAMP LHS	1	\$ x 262.19
12	MC147414	TAIL LAMP RHS	1	\$ x 262.19
13	MC849505	REAR NUMBER PLATE LAMP	1	\$ x 65.93
14	MC030738	REAR CHASSIS CROSSMEMBER	1	\$ <i>bt</i> 500.50 x
SUB-TOTAL :				\$ 6,178.99
LESS 25% :				\$ 1,544.75
BALANCE :				\$ 4,634.24
<b>SPECIAL-NETT ITEMS</b>				
1		REAR BUMPER	1	\$ <i>bt</i> 950.00
2		REAR BUMPER BRACKET LHS/RHS	2	\$ x 400.00
3		REAR/FRONT NUMBER PLATE	1	\$ <i>bt</i> 40.00
4		REAR STEP PANEL	1	\$ <i>bt</i> 450.00
5		TAIL LAMP HOLDER LHS/RHS	1	\$ x 360.00
6		YELLOW/BLACK STICKER	1	\$ x 20.00
PARTS TOTAL :				\$ 6,854.24



Certificate No: AJA15101243 Certificate No: AJA210554



# GOLDBELL ENGINEERING

Industrial Vehicles.  
20,000 Served. And Counting.

## LABOUR CHARGES

1 TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	600.	1500.	\$ 4,000.00
2 TO CHECK FOR & RECTIFY WIRING FAULTS, ETC. TO CARRY OUT DIAGNOSTICS CHECK.		✓ 1225.	\$ 200.00
3 TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC.			\$ 2,100.00
4 SUNDRIES			\$ 30.80.00
LABOUR TOTAL :			<u>\$ 6,380.00</u>
GRAND TOTAL :			<u><u>\$ 13,234.24</u></u>

PREPARED BY : WILLIAM GO

DATE / TIME : 6/12/16 @ 1520

SURVEYOR : Tanpin

MOBILE NO. : 97495744

OFFICE FAX NO. : \_\_\_\_\_

EMAIL ADDRESS : tanpin@ukauto.com

REPAIR TYPE : PART-BY-PART / LUMP SUM

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 6 days

REMARKS : \_\_\_\_\_

5824.60  
1519.07  
7343.67

"WP"



Certificate No: AJA(S)01/Q1243      Certificate No: AJA01/2654