

Date: 28.01.2021  
 Vehicle No: EV9983D  
 Model: SUBARU LEVORG 1.6GT-S AWD CVT  
 Chassis: JF1VM4K55GG002311  
 Reg.Year: 2015

Third Party Insurer: AIG  
 Third Party Veh No: SLC5619A  
 Date of Accident: 27.01.2021

*NOT Attached  
 Summary After Paint 2x4x5*

### ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	HEADLAMP LH 2304.00	1		\$2,360.00 ✓
2	HEADLAMP LOWER BRACKET LH	1		\$55.40 X
3	BONNET	1		REPAIR
SUB TOTAL				\$2,415.40
LESS 20% 25%				-\$483.08
PARTS TOTAL				\$1,932.32

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		\$75.00 X NN
S/N TOTAL				\$75.00

### LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, & READJUST REAR ACCIDENT AREA.

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREA.

LABOUR CHARGES TO REMOVE & RE-FIT FRONT BUMPER (INSTALLATION OF HEADLAMP)

TO CONDUCT HEADLAMP MODULE DECODING.

TO CHECK WIRING & ELECTRICAL SYSTEM.

TO DAIGNOSIS FAULT CODE & RESET MEMORY

TO TUFF KOTE & UNDERSEAL MATERIALS.

*150*  
 \$400.00  
 \$500.00 *220*  
 \$120.00 X  
 \$200.00 ✓ 80  
 \$150.00 *20*  
 \$150.00 ✓ 60  
 NN \$120.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL \$1,370.00  
 TOTAL \$3,302.32

Vic

Acknowledged by Repairer  
 Signature:  
 Date:

Head office  
 8 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1213 | Fax: (+65) 6472 2112

Branch  
 8A Serangoon North Ave 5 Singapore 554800  
 Tel: (+65) 6484 0019 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)  
 Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

