

Shiau Chan (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Thursday, 9 September 2021 2:36 pm
To: Shiau Chan (LKKAuto)
Subject: RE: CTI-TP SLW 5617A SURVEYED BY TAUFIKH (OUR REF: CS/CTI21001413/T1qd3)

Dear Shiau Chan,

AUDIT CHECK DONE FOR SLW5617A, FOUND NO WHEEL ALIGNMENT REPORT FOR UNDERCARRIAGE PARTS REPLACED.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAuto)
Sent: Thursday, 9 September, 2021 12:03 PM
To: Simon Ho (LKKAuto)
Subject: CTI-TP SLW 5617A SURVEYED BY TAUFIKH (OUR REF: CS/CTI21001413/T1qd3)

Dear Simon,

For your audit.

Thank you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)