

## Shiau Chan (LKKAuto)

---

**From:** Simon Ho (LKKAuto)  
**Sent:** Friday, 10 September 2021 4:28 PM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** RE: CTI-TP SLW 5617A SURVEYED BY TAUFIKH (OUR REF: CS/CTI21001413/T1qd3)

Dear Shiau Chan,

Audit check done for SLW5617A without problem.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Friday, 10 September, 2021 3:05 PM  
**To:** Simon Ho (LKKAuto)  
**Subject:** RE: CTI-TP SLW 5617A SURVEYED BY TAUFIKH (OUR REF: CS/CTI21001413/T1qd3)

Dear Simon,

For your re-audit.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Simon Ho (LKKAuto) <[SimonHo@lkkauto.com](mailto:SimonHo@lkkauto.com)>  
**Sent:** Thursday, 9 September 2021 5:16 PM  
**To:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Subject:** RE: CTI-TP SLW 5617A SURVEYED BY TAUFIKH (OUR REF: CS/CTI21001413/T1qd3)

Dear Shiau Chan,

AUDIT CHECK DONE FOR SLW5617A, FOUND LOD & SURVEYOR REPORT SMALL GAP SHOULD REVIEW TO CONCLUDE.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Shiau Chan (LKKAuto)

**Sent:** Thursday, 9 September, 2021 4:11 PM

**To:** Simon Ho (LKKAuto)

**Subject:** RE: CTI-TP SLW 5617A SURVEYED BY TAUFIKH (OUR REF: CS/CTI21001413/T1qd3)

Dear Simon,

For your re-audit. Wheel alignment report uploaded.

Thank you.

Best Regards,

Shiau Chan (Ms) | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Simon Ho (LKKAuto) <[SimonHo@lkkauto.com](mailto:SimonHo@lkkauto.com)>

**Sent:** Thursday, 9 September 2021 2:36 pm

**To:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>

**Subject:** RE: CTI-TP SLW 5617A SURVEYED BY TAUFIKH (OUR REF: CS/CTI21001413/T1qd3)

Dear Shiau Chan,

AUDIT CHECK DONE FOR SLW5617A, FOUND NO WHEEL ALIGNMENT REPORT FOR UNDERCARRIAGE PARTS REPLACED.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Shiao Chan (LKKAuto)  
**Sent:** Thursday, 9 September, 2021 12:03 PM  
**To:** Simon Ho (LKKAuto)  
**Subject:** CTI-TP SLW 5617A SURVEYED BY TAUFIKH (OUR REF: CS/CTI21001413/T1qd3)

Dear Simon,

For your audit.

Thank you.

Best Regards,

Shiao Chan (Ms) | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)