

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Date of Estimate: 01.02.2021
Vehicle No: GBE1382R
Owner: SPRINGHILLS IMPEX AND TRADING PTE LTD
Date of Accident: 28.01.2021
Make & Model: FIAT DOBLO
Chassis No : ZFA26300006A85856

ESTIMATE FOR ACCIDENT VEHICLE NO GBE1382R

PARTS

- | | | | |
|----|---|------------------------------|---------|
| 1 | 1 | Rear door LH | 1525.30 |
| 2 | 1 | Rear door handle garnish LH | |
| 3 | 1 | Rear door Electric lock LH | |
| 4 | 1 | Rear door inner garnish LH | |
| 5 | 2 | Rear door hinge LH | |
| 6 | 1 | Rear door RH | 1420.40 |
| 7 | 1 | Rear door handle garnish RH | 321.80 |
| 8 | 1 | Rear door inner garnish RH | |
| 9 | 1 | Rear door lock RH | 302.70 |
| 10 | 1 | Rear door hinge | |
| 11 | 1 | Emblem *DOBLO* | |
| 12 | 1 | Emblem *MAXI* | |
| 13 | 1 | Emblem *FIAT* | |
| 14 | 1 | Emblem *PROFESSIONAL* | |
| 15 | 1 | Emblem *90 MULTIJET* | |
| 16 | 1 | Rear bumper | 627 |
| 17 | 1 | Rear bumper tow cover | |
| 18 | 1 | Rear bumper support | |
| 19 | 1 | Rear bumper bracket LH/RH | |
| 20 | 1 | Rear bumper reflector LH/RH | |
| 21 | 1 | Tail lamp LH/RH | |
| 22 | 1 | Weather strip rear | 430.80 |
| 23 | 1 | End cross member panel | 187.60 |
| 24 | 1 | End cross member top garnish | |

LKK Auto Consultants hence notify the Repairer of the following:
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

@ \$88.00

@ \$88.00

@ \$78.00

@ \$68.20

@ \$480.00

SUB TOTAL
LESS 10 %
DISCOUNTED SUB TOTAL

Ry	\$2,235.50	✓	368-20
war	\$625.00	✓	
Sm	\$355.20	X	
On	\$233.50	✓	
R	\$176.00	X	
Ry	\$1,998.30	✓	
Sm	\$389.60	✓	
Sm	\$178.20	✓	
On	\$389.00	✓	
R	\$176.00	X	
Ne	\$118.00	✓	
Ne	\$98.00	✓	
Ne	\$168.00	✓	
Ne	\$110.00	✓	
Ne	\$98.00	✓	
CM / Pd	\$898.20	✓	
Sm	\$36.20	X	
Sm	\$165.00	X	
R	\$156.00	X	
Sm	\$136.40	X	
Sm	\$960.00	X	
Net/Sm	\$223.10	50% ✓	
Ry	\$786.80	✓	
CM	\$238.00	✓	
SUB TOTAL		\$10,948.00	
LESS 10 %		\$1,094.80	
DISCOUNTED SUB TOTAL		\$9,853.20	

S. NETT ITEM

- | | |
|---|--------------------------------|
| 1 | 1set Front bumper clips |
| 2 | 2 Windscreen sealant X 2 doors |
| 3 | 1 70KM sticker |
| 4 | 1 6 PAX sticker |
| 5 | 1set Reverse sensor |
| 6 | 1 Number plate & garnish |
| 7 | 1 Rear cam |

SUB TOTAL
LESS 0 %
DISCOUNTED SUB TOTAL

Ne	\$50.00	✓
Ne	\$180.00	80% ✓
Ne	\$15.00	12% ✓
Ne	\$15.00	12% ✓
Short	\$280.00	✓
Net	\$80.00	45% ✓
Sm	\$380.00	X
SUB TOTAL		\$1,000.00
LESS 0 %		\$0.00
DISCOUNTED SUB TOTAL		\$1,000.00

LABOUR

- | | |
|---|---|
| 1 | Panel beating for replace and repair affected parts |
| 2 | Spray painting on accident areas |
| 3 | Wiring charges |
| 4 | Apply undercoating to above affected areas |
| 5 | Remove/refix rear door X 2 mechanism |
| 6 | Remove/refix windscreen X 2 |

SUB TOTAL (LABOUR)

\$1,000.00	50% ✓	
\$1,000.00	75% ✓	
\$100.00	20% ✓	
\$120.00	60% ✓	
\$240.00	120% ✓	
\$360.00	160% ✓	
SUB TOTAL (LABOUR)		\$2,820.00