

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Koh Ming Shao

Date: 10 May 2021

Preliminary Advice

Insured Vehicle No	: PC6786X	Accident Date	: 25/01/2021
TP Vehicle No	: FBB3815L	Assignment Date	: 29/01/2021
Make	: YAMAHA RXZ	Est. Duration of Repair	: 4
Date of Inspection	: 29/01/2021		
Inspection At	: SG 98 MOTOR PTE LTD (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,857.20
Revised Amount	:S\$	2,512.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,512.10

Lump Sum Repair	:S\$	2,000.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.