

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 25 Jun 2021

## **Preliminary Advice**

Insured : SLQ9846K  
Vehicle No  
TP Vehicle No : SHC156Z  
Accident Date : 29/01/2021  
Make : TOYOTA PRIUS HYBRID  
Assignment Date : 29/01/2021  
Date of Inspection : 01/02/2021  
Est. Duration of Repair : 7  
Inspection At : BIFROST AUTO PTE LTD (SIN MING) (HQ)  
BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE  
SINGAPORE 575644

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,913.00
Revised Amount	:S\$	12,448.59
Check Items (Estimated)	:S\$	0.00
Total	:S\$	12,448.59

Lump Sum Repair	:S\$	9,950.00
-----------------	------	----------

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

**Remarks**

( ) The vehicle is economical for repair

( ) The vehicle is not economical for repair

( ) Part-by-Part repair

( X ) Lump Sum repair

( X ) The above survey was conducted on a 'without prejudice' basis.