



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 687S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	SERVICEABLE	572.80	-
1	SET FRONT BUMPER CLIPS	NOT NECESSARY	50.00	-
1	FRONT BUMPER FOG LAMP COVER - LH	SERVICEABLE	95.10	-
1	FRONT BUMPER FOG LAMP GARNISH - LH	SERVICEABLE	85.00	-
1	FRONT BUMPER SIDE RETAINER - LH	SERVICEABLE	137.20	-
1	FRONT CORNER FENDER - LH	TO REPAIR SEE LABOUR	223.90	-
1	FRONT DOOR - LH	BENT	1,268.50	1,268.50
1	FRONT DOOR HINGE BOTTOM - LH	TO REPAIR SEE LABOUR	82.50	-
1	FRONT DOOR LOCK - LH	TO REPAIR SEE LABOUR	320.00	-
1	FRONT DOOR REGULATOR - LH	* CHECK	280.00	-
1	FRONT DOOR STICKER - LH	NECESSARY	25.00	25.00
1	FRONT GRILLE	SERVICEABLE	335.10	-
1	SET FRONT GRILLE CLIPS	NOT NECESSARY	30.00	-
1	FRONT HEADLAMP - LH	SERVICEABLE	858.40	-
1	FRONT SIDE LAMP - LH	SERVICEABLE	195.20	-
1	FRONT STEP GARNISH - LH	SERVICEABLE	185.00	-
1	FRONT STEP INNER PANEL - LH	BENT	265.00	265.00
1	FRONT STEP PANEL TOP GARNISH	SERVICEABLE	165.10	-
1	REAR SLIDING DOOR - LH	BENT	1,480.00	1,480.00
1	REAR SLIDING DOOR HINGE - LH (TOP)	* CHECK	186.40	-
1	REAR SLIDING DOOR HINGE CENTRE	* CHECK	220.85	-
1	REAR SLIDING DOOR LOCKER PANEL STEP COVER - LH	SERVICEABLE	225.50	-
1	REAR SLIDING DOOR LOWER HINGE - LH	* CHECK	230.90	-
1	REAR SLIDING DOOR OUTER HANDLE - LH	SERVICEABLE	126.40	-
1	REAR SLIDING DOOR TRIM BOARD	SERVICEABLE	380.55	-
1	REAR SLIDING DOOR INNER LOCK - LH	TO REPAIR SEE LABOUR	380.45	-
1	REAR SLIDING DOOR HOLDER - LH	SERVICEABLE	85.15	-
1	REAR SLIDING DOOR LOWER LOCK - LH	* CHECK	280.15	-

Report Ref No. CS/SMO21001422/Kqd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SLIDING DOOR CENTRE LOCK BRACKET - LH LESS 25% DISCOUNT	* CHECK	230.15	-
			-	-759.62
			9,000.30	2,278.88
	<b>LABOUR</b>			
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF FRONT CORNER FENDER - LH, FRONT DOOR HINGE BOTTOM - LH, FRONT DOOR LOCK - LH AND REAR SLIDING DOOR INNER LOCK - LH.		1,200.00	800.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		1,200.00	800.00
	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.		150.00	90.00
	LABOUR TO REMOVE AND REPLACE FRONT DOOR COMPONENTS.		200.00	120.00
	TO CHECK WIRING FUNCTIONS.		100.00	20.00
			2,850.00	1,830.00
<b>GRAND TOTAL</b>			<b>11,850.30</b>	<b>4,108.88</b>

<b>RECOMMENDED COST OF REPAIRS (EXCLUDE CHECK ITEMS S\$1,071.34 NETT)</b>			<b>4,108.88</b>
---	--	--	-----------------

Report Ref No. CS/SMO21001422/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.