

AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998      Email : auburnauto.insurance@gmail.com

Make & Model : Toyota

Axio

Vehicle Number : SMU8839E

Quantity	Description	Repairer's Estimate
	<b><u>SIDE</u></b>	
1	Bumper Clip Right	\$150
1	Bumper Strip	\$200
1	Right Side Fender	\$250
1	Condenser	\$450
1	Radiator	\$450
1	Reinforcement Bar Sponge	\$450
	<b><u>LABOUR &amp; MISC</u></b>	
1	Checking of wiring, lighting and resetting	\$300
1	Remove and refit rear undercarriage	\$500
1	Wheel alignment	\$100
1	Remove and replace damaged parts	\$800
1	Apply undercoating on repaired and replaced panel	\$800
1	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,500
1	Respray including polishing and waxing on the changed body parts, repaired portortions where consistent to the accident	\$1,000
	<b>Total Repair Cost :</b>	<b>\$6,950</b>