



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfactori

Yap See Wee Benjamin
14 Ang Mo Kio St 63
Block B
Singapore 569116

KGC WORKSHOP
Sincere • Secure • Satisfaction
14 Ang Mo Kio St.63, Block B (S) 569116
Tel : 6453 6279 / 6456 5410
Email : contact@kgcworkshop.com.sg

TP
Date 9/3/2021
No of Page : 1/1

Registraion No : SKA 8289X
Accident Date : 22-Jan-21
Our Ref : TP

*NOT Authorized
L1 Sy @ 1850/hr
Permy After Pain
4 days*

Model : Daihatsu Terios
Chassis No: JDAJ210G001058746
Engine Capacity :

| S/No | Qty | Items | Unit Price | Amount |
|------------------------------|-----|-------------------------------|------------|-----------------------|
| 1 | 1 | Front Bumper <i>560</i> | \$ 605.00 | \$ <i>Bu</i> 605.00 ✓ |
| 2 | 1 | Front Bumper Retainer RHS | \$ 48.50 | \$ <i>na</i> 48.50 ✓ |
| 3 | 1 | Headlamp RHS <i>659</i> | \$ 725.50 | \$ <i>na</i> 725.50 ✓ |
| 4 | 1 | Front Bumper reinforcement | \$ 388.20 | \$ <i>na</i> 388.20 X |
| 5 | 1 | Front Fender RHS <i>360</i> | \$ 425.50 | \$ <i>Bu</i> 425.50 ✓ |
| 6 | 1 | Front Fender Inner Shield RHS | \$ 155.50 | \$ <i>na</i> 155.50 X |
| 7 | 1 | Front Grille | \$ 405.50 | \$ <i>na</i> 405.50 X |
| 8 | 1 | Front lower Grille | \$ 285.50 | \$ <i>na</i> 285.50 X |
| 9 | 1 | Front Fog Lamp RHS | \$ 350.00 | \$ <i>na</i> 350.00 X |
| 10 | 1 | Front Fog Lamp Cover RHS | \$ 85.20 | \$ <i>na</i> 85.20 X |
| | | | | \$ 3,039.20 |
| | | | | -15% \$ 455.88 |
| Total for spare parts | | | | \$ 2,583.32 |

Special Nett

| | | | | |
|------------------------------|-------|--------------------|----------|----------------------|
| 1 | 1 set | Front Bumper Clips | \$ 50.00 | \$ <i>na</i> 50.00 ✓ |
| 2 | 1 set | Front Number plate | \$ 50.00 | \$ <i>na</i> 50.00 X |
| Total for SP | | | | \$ 100.00 |
| Sub-Total for Parts : | | | | \$ 2,683.32 |

| S/No | Qty | Items | Unit Price | Amount |
|------|-----|--|------------|-------------------|
| 1 | | To dismantle, replace, cut, weld, knock out dents to straighten accident parts | \$ | 800.00 <i>400</i> |
| 2 | | To putty and spray paint on all accident damage parts and other accident | \$ | 800.00 <i>400</i> |
| 3 | | Wheel Alignment | \$ | <i>na</i> 80.00 X |
| 4 | | To check wiring system to facilitate repair and refit the same | \$ | 80.00 <i>200</i> |
| 5 | | Apply rust proofing on the adjacent panels | \$ | 50.00 <i>300</i> |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price to be displayed
- Third party surveys on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TOTAL AMOUNT : 1,810.00

OVERALL COST : 4,493.32