

VEHICLE REPAIR ESTIMATE

Insurance Company: CHINA TAIPING INSURANCE(SINGAPORE) PTE LTD

Address: NO 3, ANSON ROAD, #16-00,
SPRINGLEAF TOWER, S(079909)

Telephone: 63896111 Fax: 62221033

Email: e-claims@sg.cntaiping.com
claimsdept@sg.cntaiping.com

Make/ Model : TOYOTA PRIUS

Date: 02.02.2021

Chassis No : JTDKD3B3501502261

Vehicle No: SKE6253R

Date/Time of Accide 28.01.2021/ 1110

Year of Reg: 21.03.2012

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	TAILGATE <i>Dented</i>	1	\$ 987.60		\$ ✓ 987.60
2	TAILGATE INNER TRIM <i>new</i>	1	\$ 345.80		\$ + 345.80
3	TAILGATE INNER LOCK <i>Dented</i>	1	\$ 254.20		\$ ✓ 254.20
4	TAILGATE LOCK CATCH <i>new</i>	1	\$ 54.20		\$ + 54.20
5	TAILGATE LOGO <i>new</i>	1	\$ 98.70		\$ ✓ 98.70
6	TAILGATE TOYOTA EMBLEM <i>new</i>	1	\$ 97.60		\$ ✓ 97.60
7	TAILGATE PRIUS C EMBLEM <i>new</i>	1	\$ 98.20		\$ ✓ 98.20
8	TAILGATE HYBRID EMBLEM <i>new</i>	1	\$ 95.80		\$ ✓ 95.80
9	TAILGATE OUTER GARNISH <i>2 new</i>	1	\$ 315.30		\$ + 315.30
10	TAILGATE WEATHERSTRIP <i>1 set</i>	1	\$ 198.60		\$ ✓ 198.60
11	TAILGATE STOPPERS <i>2 new</i>	2	\$ 35.00		\$ + 70.00
12	REAR BUMPER <i>Dented</i>	1	\$ 645.30		\$ ✓ 645.30
13	REAR BUMPER RETAINERS <i>new</i>	2	\$ 89.50		\$ ✓ 179.00
14	REAR BUMPER ANTENNA <i>new</i>	1	\$ 285.90		\$ ✓ 285.90
15	REAR BUMPER REINFORCEMENT <i>new</i>	1	\$ 428.90		\$ + 428.90
16	REAR BUMPER LOWER COVER <i>new Dented</i>	1	\$ 225.80		\$ ✓ 225.80
17	TAILAMPS <i>RA new</i>	2	\$ 358.90		\$ 358.90 717.80
18	TAILAMPS LOWER BRACKETS <i>new</i>	2	\$ 86.50		\$ + 173.00
19	TAILAMPS INNER SEALER <i>RA new</i>	2	\$ 40.00		\$ + 80.00
20	REAR FENDERS INNER TRIM <i>3 new</i>	2	\$ 385.90		\$ + 771.80
21	REAR FENDERS AIR DUCT <i>new</i>	2	\$ 98.70		\$ + 197.40
22	REAR FENDERS INNER COWLING <i>new new</i>	2	\$ 198.50		\$ + 397.00
23	REAR END PANEL <i>Repis</i>	1	\$ 532.60		\$ + 532.60
24	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 185.20		\$ + 185.20
25	WINDSCREEN MOLDING <i>new</i>	1	\$ 185.20		\$ ✓ 185.20

Total List Price Cost

PARTS DISCOUNT 25%

\$ 5,715.68

3896
2922

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING <i>NH</i>	1SET	\$ 50.00		\$ 50.00 50.00
2	REAR BUMPER CLIPS <i>NH</i>	1 SET	\$ 30.00		\$ 30.00 30.00
3	REVERSE SENSORS <i>Damaged</i>	1 SET	\$ 250.00		\$ 250.00 250.00
4	REAR FENDER INNER TRIM CLIPS <i>2 set</i>	2 SET	\$ 30.00		\$ 60.00 60.00
5	REAR FENDER INNER COWLING CLIPS <i>2 set</i>	2 SET	\$ 30.00		\$ 60.00 60.00
6	REAR BUMPER LOWER COVER CLIPS <i>1 set</i>	1 SET	\$ 30.00		\$ 30.00 30.00
7	WINMDScreen SEALANT <i>NH</i>	2	\$ 60.00		\$ 60.00 60.00
Total Special Nett Items					\$ 540.00
Labour Works/ Panel Beating Related Works					
Job Scope					Quotation
TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN AND ALIGNE ALL PARTS					\$ 1,600.00
Spray Painting					
Job Scope					Quotation
TO RESPRAY AFFECTED AREAS					\$ 1,600.00
Others Cost (Accident Repair Related Expenses)					
Job Scope					Quotation
TO TUFFCOAT AFFECTED AREA					\$ 200.00 60
TO REMOVE/ REFIT INTERIOR UPHOLSTERY					\$ 150.00 60
TO APPLY SEALANT TO THE AFFECTED AREAS					\$ 150.00 30
TO REMOVE/ REFIT WIRING CHECKS ON TAILAMPS					\$ 150.00 30
TO REMOVE /REFIT REAR WINDSCREEN					\$ 120.00 1480
TO CONDUCT WATER LEAKAGE TEST					\$ 150.00 50
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING					\$ 150.00 80
TO REMOVE /REFIT AND REPLACE TAILGATE MECHANISM					\$ 120.00 80
Total Others Cost					\$ 1,190.00
GRAND TOTAL				\$ 10,645.68	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
L/S 02/02/21
05 Days

total: 4682
L/S: 3-7K