



E & CARRIAGE

Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Angelika Gottfriede Maria Saake Reg No/Reg Date S1528CD / 20/10/201 Date In/Mileage / 0 Chassis No KNAPN81AMG7132438 Engine No G4NAGH879467 Make/Model KIA/SPORTAGE 2.0 A G416 Colour/Trim KCS SPARKLING SILVE/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	28/01/2021/ 17:55		261 / Edwin Caina	23347

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 TO REPLACE FRT LH DOOR, REAR LH DOOR, LH SIDE SILL MOULDING & AFFECTED AREA	80	20.00		1600.00
E PNT98000 PAINT WORK FRT LH DOOR, REAR LH DOOR & REAR BUMPER	350 x 2	3.00		1050.00
E PNT88000 TO REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR		1.50		150.00
E PNT88000 TO TRANSFER FRT LH DOOR ATTACHMENT TO NEW PANEL		1.50		150.00
E PNT88000 TO TRANSFER REAR LH DOOR ATTACHMENT TO NEW PANEL		1.50		150.00
M SUNDRY PERFORM RUST PREVENTION		1.50		120.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA		0.80		80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM		1.50		200.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST		0.50		50.00
M SUNDRY TO TRANSFER REAR LH RIM INCLUDING BALANCING		1.80		180.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment		0.50		50.00
M SUNDRY SUNDRIES	1.00	655.00	20.00	655.20
M PANEL ASSY-REAR DOOR, LH	1.00	776.00	20.00	776.00
M PANEL ASSY-FRONT DOOR, LH	1.00	102.40	20.00	102.40
M GARNISH ASSY-QTR SIDE, LH	1.00	124.80	20.00	124.80
M GARNISH ASSY-FNDR SIDE LH	1.00	365.60	20.00	365.60
M COVER-RR BUMPER LWR	1.00	204.00	20.00	204.00
M GUARD ASSY-REAR WHEEL, LH	1.00	884.00	20.00	884.00
M WHEEL ASSY-ALUMINIUM	1.00			

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Angelika Gottfriede Maria Saake Reg No/Reg Date S1528CD / 20/10/201 Date In/Mileage / 0 Chassis No KNAPN81AMG7132438 Engine No G4NAGH879467 Make/Model KIA/SPORTAGE 2.0 A G416 Colour/Trim KCS SPARKLING SILVE/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	28/01/2021/ 17:55		261 / Edwin Caina	23347

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M MOULDING ASSY-SIDE SILL,LH ✓ CHJ	1.00	265.00	20.00	212.00

Estimate

SURVEYOR NAME: Steve (LKK) 1/2/21, 10.50am
 SURVEYOR SIGNATURE: OO-NM AL
 DATE: PIP
 REMARKS: Excess - ?
By Bel SM
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Trade prices are subject to confirmation

Confirm & accepted by survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Authorized signatory and company stamp	7% GST on	7224.00	7,224.00
	Nett	505.68	7,729.68
	Total Payable	7,729.68	

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.