

Our Job Ref No : 305451249

Date : 21.02.21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr GUO QIANG

Vehicle Reg No. : SHC1348E CTPL

30.01.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **NTUC** **SKD5573D**

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$2,400.00

Final Lumpsum Repair cost **\$2,400.00**

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature :

Name : LIM KWOK ENG

Name :

Tel : 62148316

Date :

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT & ENGINEERING

VEHICLE NO. : SHC1348E

MODEL IONIQ (G2)

JOB NO 305451249

TYPE OF CASE : TP-

SURVEY BY : LKR/GUO QIANG

DATE : 01/02/2021

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

[illegible]

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305451249
 REGN NO : SHC1348E
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 13.09.2018
 DATE/TIME IN : 30.01.2021 01:20
 ACCIDENT DATE : 30.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1 L	459.40	20.00	367.52	/ Dis
0002	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/ MC
0003	04-01-0104-2288-G	BEAM-RR BUMPER	1 L	394.80	20.00	315.84	/ BT
0004	04-01-0104-3819-G	STAY-RR BUMPER LH	1 L	138.10	20.00	110.48	- BT
0005	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1 L	451.25	20.00	361.00	/ Dis
0006	04-01-0104-2544-G	CAP-RR HOOK	1 L	98.80	20.00	79.04	/ Dis
0007	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1.000	N/ 180.00	10.00	162.00	/ OM
0008	04-01-0104-2531-G	BRACKET ASSY-RR BUMPER SI	1 L	55.80	20.00	44.64	/ Cut.
0009	04-01-0104-2370-G	LAMP ASSY-REAR FOG	1 L	201.50	20.00	161.20	? ✓ part taken
0010	04-01-0104-2226-G	LAMP ASSY-LICENSE PLATE	1 L	85.30	20.00	68.24	✓ NIS
0011	04-01-0104-0851-G	REFLECTOR/REFLEX ASSY-RR	1 L	41.45	20.00	33.16	? X
0012	FNPS	NUMBER PLATE WITH TRIM CO	1 N/	55.00	10.00	49.50	/ Dis
0013	04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1 L	155.00	20.00	124.00	/ Cut.

S Smartkey Antenna Assy - \$40.50

2,085.45
 +? 309.50

2,394.95
 → +Suppl. 40.50

2,435.45
 -20%

+Nett 1,948.36
 → 211.50
 2,159.86

COMFORTDELGRO ENGINEERING PTE LTD

Date: 01.02.2021

REPAIR ESTIMATE

Time: 12:16:59

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305451249
 REGN NO : SHC1348E
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 13.09.2018
 DATE/TIME IN : 30.01.2021 01:2
 ACCIDENT DATE : 30.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0104-2540-G	COVER-RR BPR UNDER CTR	1 L	225.00	20.00	180.00	✓ DTS
15 04-01-0104-2546-G	COVER-RR BUMPER SIDE UNDER	Lh 1 L	108.00	20.00	86.40	? ✓ part taken
0016 09-01-0104-2184-G	UNIT ASSY-BSD LH	1 L	1,625.00	20.00	1,300.00	?
SUB-TOTAL : 3,460.62						2,159.86

JOB NATURE

0000 23-01	TOWING FEE	60.00	X	
0001 20-05	REAR FENDER ADVERTISEMENT LOGO LH	100.00	✓	
0002 20-05	REAR FENDER ADVERTISEMENT LOGO RH	100.00	✓	
0003 L	PANEL BEATING	400.00	350	
0004 23-502	SPRAYPAINT ON AFFECTED AREA	300.00	250	
0005 17-01	CHECK ALL LIGHTING	50.00	30	
				200 670 870 3,029.86 - 202 2,423.88

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305451249
REGN NO : SHC1348E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 13.09.2018
DATE/TIME IN : 30.01.2021 01:2
ACCIDENT DATE : 30.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0006 20-22 REMOVE/REFIX REVERSE SENSOR
007 L DIAGNOS & RESET BSD ASSY FAULT CODE

120.00

40

480.00

?

SUB-TOTAL : 1,610.00

TOTAL : 5,070.62

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

2 Days 4/5 \$ 2,400/-

P/P 6/8 Carpin Repair

After ~~the~~ paint photos.

Guro Qs up

01/2/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: