



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKZ2166A*RA

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **48076**
Reg No/Reg Date **SKZ2166A*RA / 14/01/2016**
Date In/Mileage **02/02/2021/ 38123**
Chassis No **WDQ1569422J123873**
Engine No **27091030642606**
Make/Model **MB/GLA 180 (X156) "URBAN"**
Colour/Trim **025 589 Jupiter Re/ 043 361 ARTICO Laro**

Account No	Terms	Date/Time Printed	CSE	Operator	
WC000668	Credit	24/02/2021/ 17:09	VS	356 / Vincent Seah	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUB

POLICY NO/ACC DATE : DMPCSNW00009842101 // 28.01.2021
TOW IN/EXCESS : 28.01.2021 // \$500
DATE IN/DATE SURVEY: 28.01.2021 // 01.02.2021 RASUL-LKK 11:00AM
BY/AUTHORIZED ON : SHIAU CHAN-LKK // 02.02.2021

S BPNTOW

STRAIGHT TOWING FROM 218 SOUTH BRIDGE RD OTR TO PLSC
USING KING DOLLEY
WO:187032

S BPNSUB

SUPPLY 1 PC NO PLATE

A BPILAB

REMOVE & REPLACE HEADLAMP WITH FOCUS ADJUSTMENT. NETT

A BPILAB

REMOVE & REPLACE ON FRONT BUMPER

A BPIRES

RESPRAY ON FRONT BUMPER

X BPNEXC

INSURANCE EXCESS

X LHF FENDER WHEEL ARCH MOULDING

X FRONT BUMPER

X LHF BUMPER MOULDING

X FRONT CENTRAL BUMPER COVER-SILVER

X ENGINE COVER LOWER SUPPORT

X LEFT INNER DISTANCE SENSOR

X SPACER RING

X LICENSE PLATE MOLDING

X LEFT HEADLAMP UNIT

150.00

60.00

120.00

960.00

600.00

-500.00

1.00 218.89 00.00 218.89

1.00 1388.72 00.00 1388.72

1.00 82.40 00.00 82.40

1.00 653.25 00.00 653.25

1.00 296.93 00.00 296.93

1.00 182.48 00.00 182.48

1.00 6.35 00.00 6.35

1.00 71.25 00.00 71.25

1.00 2581.32 00.00 2581.32

Confirmed & accepted by

3 days

Finalization

7% GST on **6871.59** **Nett 6,871.59**
481.01

Authorized signatory and company stamp

Total Payable 7,352.60

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg