



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKZ2166A*RA

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 48076
Reg No/Reg Date SKZ2166A*RA / 14/01/2016
Date In/Mileage SKZ2166A*RA / 0
Chassis No WDC1569422J123873
Engine No 27091030642606
Make/Model MB/GLA 180 (X156) "URBAN"
Colour/Trim 025 589 Jupiter Re/ 043 361 ARTICO Laro

Account No	Terms	Date/Time Printed	CSE	Operator				
WC000668	Credit	29/01/2021/ 15:16	VS	356 / Vincent Seah				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : DMPCSNW0009842101 // 28.01.2021 TOW IN/EXCESS : 28.01.2021 // DATE IN/DATE SURVEY: 28.01.2021 // BY/AUTHORIZED ON :								
S BPNTOW STRAIGHT TOWING FROM 218 SOUTH BRIDGE RD OTR TO PLSC USING KING DOLLEY WO:187032								150.00
S BPNSUB SUPPLY 1 PC NUMBER PLATE WITH HOUSING.NETT 4/- FRONT								60.00
A BPILAB REMOVE & REPLACE HEADLAMP WITH FOCUS ADJUSTMENT.NETT								120.00
A BPILAB REMOVE & REPLACE ON FRONT BUMPER								1200.00
A BPIRES RESPRAY ON FRONT BUMPER								1200.00
M LHF FENDER WHEEL ARCH MOULDING SC	1.00	218.89	00.00					218.89
M FRONT BUMPER SC	1.00	1388.72	00.00					1388.72
M IMPACT ABSORBER ? x su	1.00	155.41	00.00					155.41
M SPRING NUT ? x nn	4.00	3.52	00.00					14.08
M CENTRAL TOP TRIM BUMPER ? x su	1.00	72.47	00.00					72.47
M LHF BUMPER MOULDING SC	1.00	82.40	00.00					82.40
M RH bumper moulding inconsistent nn	1.00	82.40	00.00					82.40
M FRONT CENTRAL BUMPER COVER-SILVER CR	1.00	653.25	00.00					653.25
M ENGINE COVER LOWER SUPPORT ? x cr	1.00	296.93	00.00					296.93
M FRONT BUMPER LOWER GRILLE ? x su	1.00	137.09	00.00					137.09
M LEFT FRONT BUMPER FOGLAMP COVER x su	1.00	36.60	00.00					36.60
M COMPANY SIGN 2 x nn	1.00	63.68	00.00					63.68
M GROMMET 2 x nn ? x su	2.00	2.64	00.00					5.28
M ELECTRICAL WIRING HARNESS ? su	1.00	158.99	00.00					158.99
M OUTER LEFT DISTANCE SENSOR ? su	1.00	182.48	00.00					182.48

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop

ESTIMATE FOR SKZ2166A*RA

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 48076
Reg No/Reg Date SKZ2166A*RA / 14/01/2016
Date In/Mileage / 0
Chassis No WDC1569422J123873
Engine No 27091030642606
Make/Model MB/GLA 180 (X156) "URBAN"
Colour/Trim 025 589 Jupiter Re/ 043 361 ARTICO Laro

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	29/01/2021/ 15:16	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LEFT INNER DISTANCE SENSOR - XSVL	1.00	182.48	00.00	182.48
M SPACER RING - CM	2.00	6.35	00.00	12.70
M LICENSE PLATE MOLDING - XSVL	1.00	71.25	00.00	71.25
M LHF ARM SUPPORT - XSVL	1.00	16.62	00.00	16.62
M CROSS MEMBER - XSVL	1.00	340.68	00.00	340.68
M LEFT HEADLAMP UNIT - XSVL	1.00	2581.32	00.00	2581.32
M RADAR SENSOR - XSVL	1.00	1250.12	00.00	1250.12
M FIXTURE-RADAR - XSVL	1.00	46.30	00.00	46.30

LRK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Paul
Hp 90010068
3 days
01/02/2021 @ 1100
Excess: 500
Revert
Ready before pickup

Confirmed & accepted by

Nett 10,780.14
7% GST on 10780.14 754.61
Total Payable 11,534.75

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388