

Your Ref: 17/17/17/VC40/239732

Date: 02nd March 2021

Our Ref: CS1/LPM21001462/R1tf3e2

M/s Lonpac Insurance Bhd

21st Flr, Bangunan Public Bank

NO. 6 Jalan Sultan Sulaiman

50000 Kuala Lumpur, Malaysia

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJT 3664R
INSURED VEHICLE: J 3058A
ACCIDENT DATE: 07/07/2017**

We thank you for your instruction on 29/01/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJT 3664R from M/s L.B.S Auto Consultants Pte Ltd.
- b) Singapore Accident Statement of Vehicles SJT 3664R.
- c) Polis Diraja Malaysia of Vehicles J 3058A and SJT 3664R.
- d) Colour damaged vehicle photographs of SJT 3664R.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJT 3664R
Make & Model	: Toyota Prado, 2.7 (A)
Year of Registration	: 2007
Chassis Number	: TRJ1205072469
Engine Capacity	: 2693 cc

2. We recommend that the repairs of the entire damage require about 16 (Sixteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.