



Kg *Attn: Kenneth*

SMH1206X
TP/China

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Feb 2021)
Parts: M1-MPV TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SMH1206X/17/02/2021 12:03

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

*Not with claim
Primary BP party
8 4153.00 6 days*

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 PC REAR BUMPER	0.00	0.00	*250.00 F	✓
2	1		*1 PC REAR BUMPER TOW COVER	0.00	0.00	*15.00 F	✓
3	1		*1 PC REAR BUMPER SIDE RETAINER <i>LH</i>	0.00	0.00	*38.00 F	✓
4	1		*1 PC REAR BUMPER SIDE REFLECTOR	0.00	0.00	*35.00 F	X
5	1		*1 PC TAILGATE	0.00	0.00	*750.00 F	✓
6	1		*1 PC TAILGATE INNER LOCK	0.00	0.00	*200.00 F	✓
7	1		*1 PC TAILGATE INNER RUBBER	0.00	0.00	*155.00 F	✓
8	1		*1 PC TAILGATE INNER TRIM BOARD	0.00	0.00	*300.00 F	X
9	1		*1 PC TAILGATE EMBLEM (HYBRID)	0.00	0.00	*40.00 F	X
10	1		*1 PC TAILGATE CENTRE OUTER MOULDING	0.00	0.00	*380.00 F	X
11	1		*1 PC REAR WINDSCREEN GLASS MOULDING	0.00	0.00	*55.00 F	X
12	1		*1 PC REAR END PANEL OUTER	0.00	0.00	*280.00 F	X
13	1		*1 PC REAR SPARE TYRE COMPARTMENT	0.00	0.00	*450.00 F	X
14	1		*1 PC REAR LH CORNAL PANEL	0.00	0.00	*130.00 F	X
15	1		*2 PCS TAILLAMPS @280/PC	0.00	0.00	*560.00 F	X
Total Parts (S\$)						3,638.00	

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SMH1206X/17/02/2021 12:03. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 PC REAR WINDSCREEN GLASS GUM	40.00
2	1	1 SET REVERSE CAMERA	380.00
3	1	1 SET REVERSE SENSOR	200.00
Sub Total (S\$)			620.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	100.00
2	REMOVE & REFIX TAILGATE, REAR WIPER ASSY, TAILLAMPS, REAR LOCK ASSY, TO CUT, WELD & RENEW REAR END PANEL, REAR SPARE TYRE COMPARTMENT, KNOCK & REPAIR REAR FLOOR BOARD PANEL, REAR LH SIDE PANEL & REALIGN THE SAME	New	1,200.00
3	REMOVE & REFIX SEAT, CARPET, GARNISH, ETC	New	120.00
4	PUTTY & RESPRAY ON REAR L FLOOR BOARD PANEL, REAR BUMPER, TAILGATE, REAR LH SIDE PANEL	New	1,200.00
5	RUSTPROOFING	New	60.00
Gross Labour Cost (S\$)			2,680.00

Cheng Hoe Motor Pte Ltd/SMH1206X/17/02/2021 12:03. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >