

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	29/01/2021
Vehicle Reg. No.:	SHD3439H	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Vehicle Reg. Date:	11/08/2016
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDGU668335	Chassis No:	KMHLB41UMGU093282
Odometer:	478918 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	2,199.40
Miscellaneous Items	11.00
Labour	1,410.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,620.40
+ GST 7.00% (S\$)	253.43
Nett Amount (S\$)	3,873.83

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version 1.0 (Last Synchronised 01 Feb 2021)**Parts:** 143 HYUNDAI I40 1.7 D CRDI FL ABS AIRBAG 4DR (A) (Catalogue Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD3439H/01/02/2021 09:40**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk ***Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER / 2's	20.00	0.00	*1,106.00 FL
2	2		*REAR BUMPER BRACKET SIDE LH/RH X NN	20.00	0.00	*71.20 FL
3	10		*REAR BUMPER CLIPS / MC NN	20.00	0.00	*22.00 FL
4	1		*REAR BUMPER LOWER COVER X NN	20.00	0.00	*228.00 FL
5	1		*REAR BUMPER REINFORCEMENT ?	20.00	0.00	*428.40 FL
6	2		*REAR BUMPER REINFORCEMENT STAY BRACKET LH/RH ?	20.00	0.00	*160.60 FL
7	1		*REAR BUMPER REFLECTOR LH / CA	20.00	0.00	*32.00 FL
8	1		*BOOTLID MOULDING = Scr	20.00	0.00	*85.00 FL
9	1		*BOOTLID GARNISH = Ant	20.00	0.00	*227.00 FL
10	1		*BOOTLID CRDI PLATE = 3 MC	20.00	0.00	*27.90 FL
11	1		*BOOTLID I-4 PLATE	20.00	0.00	*21.90 FL
12	1		*REVERSE SENSOR / Om	0	0.00	*135.70 FS
13	1		*BOOTLID COMFORT & TEL NO STICKER / MC	0	0.00	*135.70 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)**2,681.40****- List Item Discount on L Items (\$\$)****482.00****Total Parts (\$\$)****2,199.40****ComfortDelGro Engineering Pte Ltd/SHD3439H/01/02/2021 09:40. Not valid without Reference section.**

Generated using Merimen e-Claims IEAS

2/1/2021

Repairer Estimates

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

560

600.00

2 SPARY PAINTING

New

500

600.00

3 CHECK LIGHTING

New

30

60.00

4 TUFF COATING

New

MN X

90.00

5 REMOVE/ REFIX REVERSE SENSOR

New

40

60.00

Gross Labour Cost (S\$)

1,410.00

ComfortDelGro Engineering Pte Ltd/SHD3439H/01/02/2021 09:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4 Days

4 Days.

Upon repair

After repair photos

Gina Q. Yap

01/2/2021