

Lion City Rentals Pte Ltd
 CARROS CENTER
 60 JALAN LAM HUAT #04-01 S(737869)
 Main +65 62524991

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Ms: AIG Asia Pacific Insurance
 Date: 01/02/2021
 Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLCB225H
 CHASSIS NO: NSP1707029771
 MAKE / MODEL: Toyota Sienta 1.5X Auto
 DATE OF ACCIDENT: 12/01/2021
 YOUR INSURED VEHICLE NUMBER: SMNS245A
 MILEAGE: 405751 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Front bumper cover / CRM	1PC	\$ 900.00	\$ 900.00 679
2	F/R fender / PD	1PC	\$ 720.00	\$ 720.00 /
3	F/R fender inner liner / CRT	1PC	\$ 234.00	\$ 234.00 /
4	F/R headlamp / SCR	1PC	\$ 990.00	\$ 990.00 /
5	F/R door / PD	1PC	\$ 1,610.00	\$ 1,610.00 1395
5	F/R fog lamp garnish / CRU	1PC	\$ 480.00	\$ 480.00 328
LIST TOTAL S\$:				\$ 4,934.00 4,346
25.00% DISCOUNT S\$:				\$ 1,233.50 -2590
				\$ 3,700.50 3,259.50

SPECIAL NETT

1	Bumper clips / NLC	1 SET	\$ 80.00	30
2	F/R wheel cap / CRA	1 PC	\$ 150.00	/
Special Nett Total S\$:				\$ 230.00 180

LABOUR CHARGES

1	To labour charge for removing front bumper, F/R door, F/R fender out to facilitate replacement of parts	\$ 900.00	600
2	To respray front bumper, F/R door and F/R fender	\$ 1,000.00	600

LABOUR TOTAL S\$:	\$ 1,900.00	1200
TOTAL S\$:	\$ 5,830.50	
7% GST	\$ 408.14	
GRAND TOTAL S\$:	\$ 6,238.64	

Repair day - 4 days

L/S

After claim photo

Sun Pin(LKK)

01/02/2021

TP without prejudice

3,259.50
 180
 1,200
 4,639.50
 - 20%
 3,711.60

L/S
 \$3,700
 4 days