

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 03 Feb 2021

**Preliminary Advice**

Vehicle No	: SMP5Z	Accident Date	: 02/01/2021
Make	: BMW M5	Policy No.	: DMPCSNW00170322000
Assignment Date	: 01/02/2021	Excess	: S\$4,000.00
Date of Inspection	: 02/02/2021	Est. Duration of Repair	: 6
Inspection At	: RACETECH (HQ) BLK 1 SIN MING IND ESTATE #01-103 SINGAPORE 575636		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,915.00
Revised Amount	:S\$	14,083.00
Check Items (Estimated)	:S\$	1,886.00
Total	:S\$	15,969.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	460,000.00
COE / PARF Rebate	:S\$	174,609.00
Salvage Value	:S\$	
Margin for Repair	:S\$	285,391.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :