Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)

Sent: Thursday, 4 February 2021 1:18 PM

To: Teo Roland

Cc: SUR

Subject: CHINA-OD SMP 5Z DOA: 02/01/2021

Dear Ronald,

As instructed by our client, please proceed to repair the insured vehicle **SMP 5Z with cost plus 15% instead of list prices** (Excess \$4,000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)