

96752227 Roland.

SMS

RACETECH AUTO

65544554

39 WOODLANDS CLONE (04-19) 9737050

T 65544554

to Budget Planning Department

Date : 15 Jan 2021

China Taiping Insurance (Singapore) Pte Ltd

Veh no : SMP 5 Z

3 Anson Road #15-00 Springleaf Tower

Veh : BMW M5

Singapore 079909

Policy no. :

T 63896116 F 62221033

DMPCSNW00170322000

ESTIMATED COST OF REPAIR

QTY	DESCRIPTION	AMOUNT
01	Bumper front / CRU	\$3360.00 2665 ✓
10 03	Clips / Nec.	\$36.00 5.50 ✓
01	Foam support ? (102121) CRA	\$127.00 82 ✓
01 A	Retainer / BR	\$36.00 4-221.85
01	High pressure nozzle NN? X (150748)	\$183.00 X
01 A	Mounting fender ?	\$73.00
01 A	Bracket fender ?	\$47.00
01	Number plate and holder X NN	\$50.00
01	Headlamp Adaptive LED right / CRU	\$4724.00 2900 ✓
01	Gasket / Nec.	\$130.00
02 /	Ultrasonic sensor RH / CRU. \$356	\$712.00* 85 ✓
04	Decoupling ring / NEC \$16	\$64.00
01	Side View camera / CRU.	\$791.00 720 ✓

11388-20

01	Holder camera / Nec		\$23.00	
01	Bracket camera / Nec		\$65.00	135
01	Radiator right ? ✓ CRA		\$894.00	480 ✓
01	Bracket radiator ? (151022) Nec		\$107.00	
04	Grommet radiator rec ?		\$52.00	461 + 34 = 495
01	Air guard. Surround / CRA		\$203.00**	140 ✓
01	Fender right / PP		\$1255.00	650 ✓
01	Support bracket / MIB. X NN		\$17.00	
03	Side panel brackets ? X NN	\$64.00	\$192.00	
01	Engine Compartment shielding front / CRA		\$613.00**	240 ✓ + 274 = 514
01	Holder ? CRA (150849)		\$37.00	45
01	Air duct right ? CRA (140100)		\$174.00	50 ✓
-	Technical charges to replace the above		\$2950.00	1,250 -
-	Painting		\$1900.00	700 -
-	Resetting System - inv.		\$360.00	150
-	Rust proofing		\$170.00	50 -
-	Technical charges to repair / rectify wiring		\$570.00	50 -
-	Air freight charges **		\$00	
Total			\$19,915.00	

• To verify number of item required

** To confirm air freight charges

Repair day - 6 days.

Excess = \$4,000

Sincerely

Roland Teo

PKP L/S.

OD - Rev.

After print photo.

Sun Pm (LKK)
02/02/2021.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: