

Notification Letter

Date : 01/02/2021

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
64 CECIL STREET, #04 / #05
IOB BUILDING
049711

Dear Sir / Madam,

We are instructed by **ETHOZ GROUP LTD** to notify you of a road traffic accident on **26/01/2021** at about **13:00** at **JALAN AHMAD IBRAHIM AYE (EXIT 18)** involving our client's/ customer vehicle registration number **GBG-8657-S** and vehicle registration number **SLM6152U** driven by you at the material time. A copy of Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's/ customer's vehicle has been damaged. Before our we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

Cc (other insurance companies for chain collision accident)

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 01/02/2021

To : INDIA INTERNATIONAL INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D21MTHCVE000079

Accident Date : 26/01/2021

Vehicle No : GBG-8657-S

Make & Model : TOYOTA DYNA 150 (EURO 6) 3.0 DIESEL G (M

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	TAILGATE PANEL ASSY	RESTORE	
1	TAILLAMP BRACKET RH	RESTORE	
1	END PANEL	RESTORE	
1	TAILLAMP RH	195.00	
	Sub Total	195.00	
	Discount 25% On Parts	(48.75)	
Special Nett Item			
1	REVERSE SENSOR	200.00	
1	REAR NUMBER PLATE	35.00	
1	REAR ADVERTISEMENT STICKER	150.00	

Date : 01/02/2021

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D21MTHCVE000079

Accident Date : 26/01/2021

Vehicle No : GBG-8657-S

Make & Model : TOYOTA DYNA 150 (EURO 6) 3.0 DIESEL G (M

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	385.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	600.00	
	TO RESPRAY AFFECTED AREAS	600.00	
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	
	Sub Total	1230.00	

1,761.25

Remarks:

SUB TOTAL

GST 7.0 % 123.29

TOTAL 1,884.54

Surveyor's name: _____

Principal's name: ETHOZ Group Ltd

Survey Date & Time: _____