



ESTIMATE

Our Ref: AC2021008/TP/GBJ2365H-29.01.2021

Automobile Integrated Management Pte Ltd
Co. & G.S.T. Reg no. 201605297G
Office: 61 Ubi Ave 2 #07-04 Automobile Megamart Singapore 408898
Workshop: 23 Kaki Bukit Ave 4 #04-01 (South Wing) Singapore 415933
Email: automim.claim@gmail.com Tel: 9119 8371

Man: Hsiao Tong

Not Authorized
Lian

1/1/21

2/5 \$5800 5 days

Vehicle number: GBJ2365H

Vehicle Made & Model: TOYOTA HIACE

Items	Qty	List Items	Amount \$
1	1	Tailgate	1,950.60 ✓
2	1	Tailgate glass	1,286.90 ✓
3	1	Tailgate wiper arm	110.25 X
4	1	Tailgate wiper motor	561.90 X
5	1	Tailgate view mirror	481.60 X
6	1	Tailgate logo	68.50 ✓
7	1	Tailgate sticker "HIACE"	62.60 ✓
8	1	Tailgate outer garnish	291.43 X
9	1	Tailgate inner top trim	221.41 X
10	1	Tailgate inner trim board	341.66 ✓
11	1	Tailgate inner lock	312.65 X
12	1	Tailgate inner lock actuator	296.55 X
13	1	Tailgate w/strip	228.45 X
14	2	Tailgate dampers - L/R @ 241.20	482.40 X
15	2	Tailgate side stoppers - L/R @ 48.60	97.20 X
16	2	Taillamps - L/R @ 381.65	763.30 1PC
17	1	Taillamp lower garnish	89.95 ✓
18	1	Taillamp lower garnish retainer - RH	42.20 ✓
19	1	Taillamp filler panel - RH	481.90 ✓
20	1	Rear bumper	581.60 ✓
21	2	Rear bumper side retainers - L/R @ 45.50	91.00 X
22	4	Rear bumper brackets @ 28.85	115.40 1PC
23	1	Rear end panel	871.30 ✓
24	1	Rear end panel inner member	552.60 X
25	1	Rear step panel	281.60 ✓
26	1	Rear side body panel - RH	1,486.60 X
27	1	Rear side panel air vent	110.43 ✓
28	1	Rear spare wheel carrier	311.45 X
29	1	Rear spare wheel lock catch	110.45 X
Sub-total			12,683.88
Less 25%			3,170.97
Total List			9,512.91

Vehicle number: GBJ2365H

Vehicle Make & Model: TOYOTA HIACE

Special Nett Items

30	1 set	Tailgate glass sealant	nee	80.00	40
31	1 set	Tailgate glass foam tape	nee	65.00	30
32	1	Rear wiper blade	17	40.00	X
33	1	Rear sticker "70 KM/H"	nee	10.00	✓
34	1	Rear sticker "8 PAX"	nee	10.00	✓
35	1 set	Rear reverse sensor	should	280.00	200
36	1 set	Rear reverse camera video cam		450.00	300
37	1 set	Rear bumper clip	nee	35.00	✓
Total Special Nett				<u>970.00</u>	

Labour charges

38	To check rear electrical wiring	50.00	30
39	To remove, refix tailgate glass	180.00	120
40	To transfer & reinstall tailgate components to new tailgate	150.00	60
41	To remove, refix rear reverse sensor/camera	80.00	50
42	To remove, refix rear interior trims to assist repair	120.00	X
43	To remove, refix rear exhaust systems	80.00	X
44	To respray undercoating	150.00	60
45	To respray painting and etc	1,200.00	700
46	Panel beating, cut, weld remove & replacing above parts	1,600.00	800
Total Labour		<u>3,610.00</u>	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

14,092.91

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

P-632204
452
P-474153
S/N-628
L-1900