

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC4/AIG21001483/GGA3Q2  
**Date:** 17/11/2021

**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070170560  
**Claimant Vehicle No :** SHC8302R **Insured Vehicle No :** SMW7294Y  
Date of Loss: 31/01/2021 Nature of Claim: TP Claim No: 8580259466SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SHC8302R**  
Make & Model: HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A) Engine No: G4LEKU416357  
Reg. Date: 08/01/2021 (Man. Year: 2019) Chassis No: KMHC851CVLU191846  
Colour: Blue Odometer: 4809 km  
Engine Capacity: 1580 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm  
Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,334.68	2,073.64	2,261.04	52.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	1,160.00	400.00	25.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,894.68</b>	<b>3,233.64</b>	<b>2,661.04</b>	<b>45.14</b>
<b>+ GST 7.00/7.00% (S\$)</b>	412.63	226.35	186.28	45.14
<b>Nett Amount (S\$)</b>	<b>6,307.31</b>	<b>3,459.99</b>	<b>2,847.32</b>	<b>45.14</b>
<b>+ Loss of Use (1.0 x S\$50.00/day) (S\$)</b>		50.00		
<b>+ Car Rental (4.5 x S\$125.19/day) (S\$)</b>		563.36		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,075.35</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,050.00</b>		

**INSPECTION**

Date of Assignment: 01/02/2021  
Date Inspected: 01/02/2021 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)  
59 Loyang Drive  
Singapore 508969  
Estimated Period of Repair: 3.0 days

**Adjuster:** XING GUO QIANG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR GARNISH17	Not Necessary	290.00 FL	*- FL
2	1		*FRT RH DOOR	Bent	1,797.20 FL	*1,797.20 FL
3	1		*SET FRT DOOR KEY LOCK	Not Necessary	353.50 FL	*- FL
4	1		*FRT DOOR INNER LOCK	Not Necessary	385.60 FL	*- FL
5	1		*FRT DOOR OUTER HANDLE	Distorted	234.80 FL	*234.80 FL
6	1		*FRT DOOR PROTECTOR	Cut	186.20 FL	*186.20 FL
7	1		*RR DOOR PROTECTOR	Cut	166.20 FL	*166.20 FL
8	1		*FRT RH DOOR	Repeated	1,797.20 FL	*- FL
9	1		*FRT DOOR COMFORTDEGRO STICKER	Necessary	75.00 FS	*75.00 FS
10	1		*REAR DOOR COMFORT APP	Necessary	80.00 FS	*80.00 FS
11	1		*COVER -FR DR O/S HDL RH	Necessary	13.90 FL	*13.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,379.60</b>	<b>2,553.30</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,044.92	479.66
<b>Total Parts (\$\$)</b>	<b>4,334.68</b>	<b>2,073.64</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	700.00	350.00
2	SPRAY PAINTING	New	800.00	750.00
3	TRANFER DOOR PARTS TO NEW DOOR	New	60.00	60.00
			<b>Gross Labour Cost (\$)</b>	<b>1,560.00</b>
				<b>1,160.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >