

REPAIR ESTIMATE*

VEHICLE NO SHC8302R

01/02/21

MAKE :

MODEL IONIQ G3

CHIANG/ AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRT RH ROCKER GRANISH17 X 604		NN	\$290.00
1	FRT RH DOOR X repair - 15T			\$1,797.20 ✓
1	FRT DOOR KEY LOCK SET 0.7 NN			\$353.50
1	FRT DOOR INNER LOCK X NN			\$385.60
1	FRT DOOR OUTER HANDLE - di's			\$234.80 ✓
1	FRT DOOR PROTECTOR - Sat			\$186.20 ✓
1	RR DOOR PROTECTOR - Sat			\$166.20 ✓
1	FRT RH DOOR X repeat.			\$1,797.20
	20.00% DISCOUNTED TOTAL			\$5,210.70
				\$1,042.14
				\$4,168.56
1	FRT DOOR COMFORTDEGRO STICKER - 4 pcc			\$75.00 ✓
1	REAR DOOR COMFORT APP			\$80.00 ✓
				\$155.00
	Labour Charge			
	Panel Beating			\$700.00 350
	Spray Painting			\$800.00 750
	Tranfer door part to new door.			\$60.00 -
	TOTAL LABOUR			\$1,560.00
	ESTIMATE TOTAL			\$5,883.56
				3233.64

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3 Days
P/P
before paint photos.
Gue Qs of
01/2/2021