



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
IGOR RYABCHIKOV 59 COMPASSVALE BOW #02-20 SINGAPORE 544988 Contact No	Cust No/Name KCV10680/IGOR RYABCHIKOV Reg No/Reg Date SMJ59138 / 13/03/201 Date In/Mileage 01/02/2021/ 0 Chassis No GF7W0600617 Engine No 4J11AC4847 Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994) Colour/Trim PO2 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV10680	CRDVCH	01/02/2021/ 11:06	Bod	442 / CocoLu	62517

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, REPAIR REAR FENDER LH				450 675.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, REAR FENDER LH				700.00
M SUNDRY Sundry				20.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				60.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY SUPPLY REAR LEFT TYRE				460.00
M FACE, RR BUMPER X R (Dismantle check)	1.00	807.00	00.00	807.00
M BRKT, R/BMPR FACE SIDE, LH - BR	1.00	12.00	00.00	12.00
M MOULDING, RR BUMPER, LH - CUT	1.00	106.00	00.00	106.00

Estimate

Steve (LKK) 1/2/21, 12-99pm

OO- NH ArL
EXCISE - ?
P/P
By OH sy
4 dgs

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No alteration/modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Confirm & accepted by

	Nett	2,990.00
7% GST on	2990.00	209.30
	Total Payable	3,199.30

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.