

Sin Seng Hong Spray Painting & Services

Blk 3023A Ubi Road 1, #01-63, Singapore 408717

Mobile: 96278521

Date: 29 January 2021

The Motor Claims Department
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Accident date: 25/01/2021

Policy number: DMPCSNW00087262000

SUPPLYMENTARY QUOTATION FOR SMD4678T INFINITI Q30

<u>PARTS</u>	<u>Qty</u>	<u>(\$)</u>	<u>Discount</u>	<u>(\$)</u>
Hood switch ✓ NW	1	330.00	✓ 10%	297.00
RR ABS sensor RH/LH ✓ NW	1	1,100.00	✓ 10%	990.00
Bonnet actuator ✓ NW	2	1,820.00	1755 10%	1,638.00

Total Cost of parts **2,925.00**

LABOUR

Labour charges to remove and replace parts

800.00 400

Total Cost of labour **800.00**

Total Repair Cost **3,725.00**

Yours faithfully

Andy Yeo

