

# Sin Seng Hong Spray Painting & Services

Blk 3023A Ubi Road 1, #01-63, Singapore 408717

Mobile: 96278521

Date: 29 January 2021

The Motor Claims Department  
China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

Accident date: 25/01/2021

Policy number: DMPCSNW00087262000

## REPAIR QUOTATION FOR SMD4678T INFINITI Q30

<u>PARTS</u>	<u>Qty</u>	<u>(\$)</u>	<u>Discount</u>	<u>(\$)</u>
Front bumper fascia	1	900.00	10%	810.00
Front bumper side retainer LH	1	30.00	10%	27.00
Front bumper reinforcement	1	600.00	10%	540.00
Front bumper inner foam	1	250.00	10%	225.00
Front bumper daytime running light LH	1	200.00	10%	180.00
Front bumper daytime running light garn	1	300.00	10%	270.00
Front bumper lower splash cover	1	280.00	10%	252.00
Headlamp assy LH	1	2,800.00	10%	2,520.00
LH headlamp lower bracket	1	180.00	10%	162.00
Front fender LH	1	650.00	10%	585.00
Front fender splash shield	1	220.00	10%	198.00
Front fender splash shield clip	1	80.00	10%	72.00
Front fender wheel arc garnish LH	1	480.00	10%	432.00
Front LH fender wheel arc garnish clip	10	80.00	10%	72.00
Front sport rim LH	1	1,400.00	10%	1,260.00
Front shock absorber LH	1	480.00	10%	432.00
Front lower arm LH	1	450.00	10%	405.00
Front knuckle arm LH	1	580.00	10%	522.00
Front wheel bearing w/hub assy LH	1	280.00	10%	252.00
Front tyre LH	1	200.00	10%	180.00
Front door LH	1	1,200.00	10%	1,080.00
<b>Total Cost of parts</b>				<b>10,476.00</b>

## LABOUR

Laboour charges to remove and replace, to cut and weld, to knock and reshape affected parts/areas. 600.00

Spray painting charges to putty and spray all affected parts/areas. 600.00

To remove and replace damaged left hand undercarriage and suspension parts. 450.00

To conduct computerised wheel alignment. 90.00

To check affected wiring and refocus headlamp beams. 90.00

**Total Cost of labour** **1,830.00**

**Total Repair Cost** **12,306.00**

Yours faithfully

---

Andy Yeo

