

Date: 29.01.2021
Vehicle No: SKG5030M
Model: BMW 320I
Chassis: WBAVA76090NL34627
Reg. Year: 2007

Third Party Insurer: C.TAIPING
Third Party Veh No: GBJ6072B
Date of Accident: 28.01.2021

*Not Auth orid
C1 Rmp @ 6100h
Recurry After Paint*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1	Per	\$1,100.50
2	FRONT FENDER LH	1	B	\$770.85
3	FRONT FENDER INNER SHIELD LH	1	CM	\$124.30
4	HEADLAMP LH <i>1980</i>	1	CM	\$2,223.80
5	FRONT RIM LH	1	Per	\$1,039.30
6	FRONT ABSORBER LH <i>535.80</i>	1	Per	\$584.20
7	FRONT LOWER ARM LH	1	Per	\$299.60
8	FRONT UPPER ARM LH	1	Per	\$299.60
9	FRONT KNUCKLE ARM LH <i>425</i>	1	Per	\$478.50
10	FRONT WHEEL BEARING LH <i>355</i>	1	Per	\$462.65
11	FRONT STABILIZER BAR	1	Per	\$472.45
12	FRONT STABILIZER LINK LH	1	Per	\$107.10
SUB TOTAL				\$7,962.85
LESS 5%				-\$398.14
PARTS TOTAL				\$7,564.71

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1	Per	\$75.00
2	FRONT INNER SHILED CLIPS	1	Per	\$35.00
S/N TOTAL				\$110.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REFIX, REPLACE, REPAIR & READJUST ACCIDENT AREA *4000* \$1,000.00

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA *500* \$800.00

LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. *200* \$100.00

LABOUR CHARGES TO DISMANTLED & INSTALL UNDERCARRIAGE. *200* \$250.00

TO CONDUCT WHEEL ALIGNMENT. *600* \$120.00

TO APPLY ANTI-RUST. *300* \$120.00

Vic **TOTAL** \$10,064.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

