



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10077/TONY WOO QI LUN Reg No/Reg Date SMH441P / 09/01/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH000571 Engine No 3A92UHL8844 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim W05 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	02/02/2021/ 11:10	QUD	247 / DonBong	62541			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2250.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, 450X 4.5								2025
FRONT BONNET, FRONT BUMPER FACE, RH FRONT FENDER, LH FRONT FENDER,								
REPAIR RH FRONT DOOR DAMAGE, REPAIR LH FRONT DOOR								100.00
E PNT88000								
REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO								80.00
FACILITATE REPAIR WORK								80.00
A 55900099								
TOP UP AIR CON FREE GAS AND CHECK A/CON SYSTEM								80.00
E PNT88000								
TO REMOVE AND INSTALL FRONT BODY KITS								40 120.00
M SUNDRY								
APPLY BODY SEALANT								30.00
A 54900099								
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								40 80.00
M SUNDRY								
PERFORM RUST PREVENTION								50.00
M SUNDRY								
SUPPLY FRONT NUMBER PLATE WITH FRAME								120.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								3150.00
E PNT98000								
PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, 350 X 7								2450
FRONT BUMPER, FRONT AIR DAM, RH FRONT FENDER, LH FRONT FENDER,								
RH FRONT DOOR, LH FRONT DOOR AND AFFECTED PORTION								20 50.00
M SUNDRY								
SUNDRIES					1.00	1055.00	23.00	812.35
M PANEL ASSY, FR END					1.00	65.00	23.00	50.05
M PANEL, HEADLAMP SUPPORT, UPR					1.00	758.00	23.00	583.66
M CONDENSER ASSY, A/C REFRIGE					1.00	305.00	23.00	234.85
M PIPE, A/C CONDENSER OUTLET					1.00	479.00	23.00	368.83
M MOTOR, COOLING FAN								

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10077/TONY WOO QI LUN Reg No/Reg Date SMH441P / 09/01/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH000571 Engine No 3A92UHL8844 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim W05 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	02/02/2021/ 11:10	QUD	247 / DonBong	62541			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	SHROUD, COOLING FAN	? X NM			1.00	130.00	23.00	100.10
M	FAN, COOLING, LH	? X NM			1.00	77.00	23.00	59.29
M	RADIATOR ASSY	? X NM			1.00	967.00	23.00	744.59
M	PANEL, AIR GUIDE (upper)	GR			1.00	112.00	23.00	86.24
M	TANK ASSY, RADIATOR COND	? X NM			1.00	42.00	23.00	32.34
M	LLC 4L	X NM			1.00	26.00	23.00	20.02
M	PANEL, AIR GUIDE, RH	GR			1.00	11.00	23.00	8.47
M	PANEL, AIR GUIDE, LH	GR			1.00	11.00	23.00	8.47
M	MARK, THREE-DIA	NEC			1.00	69.00	23.00	53.13
M	GRILLE, RADIATOR	GR			1.00	554.00	23.00	426.58
M	BRACKET, FR BUMPER, LH	X NM			1.00	13.00	23.00	10.01
M	BRACKET, FR BUMPER, RH	GR			1.00	13.00	23.00	10.01
M	GRILLE, FR UNDER	GR			1.00	165.00	23.00	127.05
M	GARNISH, FR BUMPER, LH	X NM			1.00	127.00	23.00	97.79
M	GARNISH, FR BUMPER, RH	X NM			1.00	127.00	23.00	97.79
M	COVER, HEADLAMP SUPT PANEL	GR			1.00	62.00	23.00	47.74
M	FACE, FR BUMPER	GR			1.00	703.00	23.00	541.31
M	COVER, FR BUMPER	CRU			1.00	13.00	23.00	10.01
M	BODY KIT, ATTRAGE	X NM			1.00	1643.00	20.00	1314.40
M	HEADLAMP ASSY, LH	GR			1.00	660.00	23.00	508.20
M	HEADLAMP ASSY, RH	GR			1.00	660.00	23.00	508.20
M	HINGE, HOOD, LH	? X NM			1.00	56.00	23.00	43.12
M	HINGE, HOOD, RH	? X NM			1.00	56.00	23.00	43.12
M	HOOD	DO			1.00	734.00	23.00	565.18
M	INSULATOR, HOOD	CRU			1.00	177.00	23.00	136.29
M	CLIP, HOOD INSULATOR	NEC			8.00	3.00	23.00	18.48
M	LATCH, HOOD	BT			1.00	69.00	23.00	53.13
M	FENDER, FR LH	DO			1.00	497.00	23.00	382.69
M	FENDER, FR RH	DO			1.00	497.00	23.00	382.69
M	EMBLEM ECO	NEC			2.00	17.00	00.00	34.00
M	COVER, FR DECK, RH	GR			1.00	16.00	23.00	12.32
M	GARNISH, FR FENDER RH	? X NM			1.00	65.00	23.00	50.05
M	GARNISH, FR FENDER LH	? X NM			1.00	65.00	23.00	50.05

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd.	Cust No/Name KCV10077/TONY WOO QI LUN
MOTOR CLAIM DEPT	Reg No/Reg Date SMH441P / 09/01/201
78 SHENTON WAY #09-16	Date In/Mileage / 0
AIG BUILDING	Chassis No MMBSTA13AKH000571
SINGAPORE 079120	Engine No 3A92UHL8844
Contact No 6419 1892	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim W05 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	02/02/2021/ 11:10	QUO	247 / DonBong	62541			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M GARNISH,FR PILLAR,RH					1.00	30.00	23.00	23.10

## Estimate

SURVEYOR NAME: Stere CLKK) 2/2/21, 12.00pmSURVEYOR SIGNATURE: OD- AM ALCDATE: EXCERS - ?REMARKS: P/PMy BL sky  
10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm &amp; accepted by

Nett	14,765.70
7% GST on	14765.70
Total Payable	15,799.30

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.